

August 3, 2011

Mr. Jeffrey Kimble On-Scene Coordinator Emergency Response Branch U.S. Environmental Protection Agency, Region 5 9311 Groh Road Grosse Ile, MI 48138

**Subject:** Final Site Assessment Report

**Rockford Paperboard Site** 

Rockford, Kent County, Michigan

Technical Direction Document No. TO-01-11-05-0012

**OTIE Contract No. EP-S5-10-10** 

Dear Mr. Kimble:

OTIE is submitting the enclosed Final Site Assessment Report for the Rockford Paperboard Site in Rockford, Michigan. If you have any questions or comments about the report or need additional copies, please contact me at (312) 220-7000 or Raghu Nagam at (312) 220-7005.

Sincerely,

Naren Babu Project Manager

mad

Enclosure

cc: Raghu Nagam, START Program Manager

### SITE ASSESSMENT REPORT ROCKFORD PAPERBOARD SITE ROCKFORD, KENT COUNTY, MICHIGAN

### Prepared for:

U.S. Environmental Protection Agency Emergency Response Branch, Region 5 77 West Jackson Boulevard Chicago, IL 60604

TDD No.: TO-01-11-05-0012 Date Prepared: August 3, 2011 Contract No.: EP-S5-10-10 Prepared by: **OTIE** START Project Manager: Naren Babu Telephone No.: (312) 220-7000 U.S. EPA On-Scene Coordinator: Jeffrey Kimble Telephone No.: (734) 692-7688



100 W Monroe Street, Suite 300 Chicago, IL 60603

## TABLE OF CONTENTS

Sec	<u>on</u> Pa	<u>ge</u>
1.	INTRODUCTION	. 1
2.	SITE BACKGROUND	. 2
2	1 Site Description	. 2
2	2 Site History	. 2
3.	SITE ASSESSMENT ACTIVITIES	. 4
3	1 Site Reconnaissance	. 4
3	2 Sampling Activities	. 6
3	2.1 Field Screening Tests	. 6
3	2.2 Analytical Sampling	. 8
4.	SAMPLE ANALYTICAL RESULTS	12
5.	POTENTIAL SITE RELATED THREATS	16
6.	SUMMARY	18
7.	REFERENCES	19
	FIGURES	
<u>Fig</u>		<u>ge</u>
1	Site Location Map	
2	Site Layout MapSample Location Map	
5		
<u>Tab</u>	TABLES Pa	<u>ge</u>
Tab Tab	e 1 Field Screening Results TruDefender and FirstDefender Analysis 2 Sampling Summary	.9 13
	APPENDICES	
A	PHOTOGRAPHIC LOG	
В	VALIDATED ANALYTICAL DATA PACKAGE	



#### 1. INTRODUCTION

OTIE has prepared this Site Assessment Report in accordance with the requirements of U.S. Environmental Protection Agency (U.S. EPA) Technical Direction Document (TDD) No. TO-01-11-05-0012 under the Superfund Technical Assessment and Response Team (START) contract No. EP-S5-10-10. The scope of this TDD was to conduct a Site Assessment at the Rockford Paperboard facility in Rockford, Kent County, Michigan. START was tasked to prepare a site-specific Health and Safety Plan, field sampling and analysis plan, subcontract an analytical laboratory, collect drum, solid and asbestos samples, evaluate analytical data, document on-site conditions with written logbook notes and still photographs, and prepare this Site Assessment Report. Naren Babu was the START Project Manager and Elisa Walker assisted with the sampling activities on June 13, 2011.

This Site Assessment Report summarizes the site background; discusses the assessment activities; provides a summary of the analytical data; and discusses potential site-related threats. The Appendix for this report includes a photographic log of the Site (Appendix A) and the validated sample analytical results (Appendix B).



#### 2. SITE BACKGROUND

This section provides Site background information and the history of the Site.


#### 2.1 Site Description

The Rockford Paperboard Site (Site) is located at 7700-7734 Childsdale in Rockford, Kent County, Michigan and is comprised of a vacant paper mill building with ancillary equipment, parking areas, lawn areas and wooded areas adjacent to the Rogue River. The geographical coordinates for the building are 43.102421 degrees latitude and -85.577036 degrees longitude (Figure 1 – Site Location Map). The Site occupies an approximate area of 17.58 acres in an industrial setting area and is surrounded by Childsdale Avenue to the northwest, a wooded area to the northeast, and Rogue River to the southeast and southwest.

#### 2.2 Site History

The Rockford Paperboard company was originally developed as a saw mill in 1848. The saw mill was later abandoned and was purchased with an additional 200 acres of surrounding property by Henry Baxter Childs in 1866. The saw mill was modified and converted in to a paper mill in 1867. Several fires in 1868 and 1898 resulted in rebuilding the mill with fire proof concrete blocks. The paper mill commenced its operations in 1899 under the name Childsdale Strawboard Mills. By 1911, the company name had changed to the Childsdale Board & Paper Co. Following several periods of inactivity during the 1920's and 1930's, the mill was purchased by Mr. Herman Gumblin in approximately 1940 and was operated by the Rockford Paper Company for box/carton production using waste/recycled paper products until 2001. The current owner, Rockford Paperboard, Inc., purchased the Site in January 1999, but the Site has been vacant for several years. Both the shallow and deep aquifer at the site is contaminated with metals and chloride above PA 451, Part 201 Generic Residential Cleanup Criteria (GRCC) of the Michigan Department of Environmental Quality (MDEQ) (Redevelopment Cost Estimate, Dec, 2011). Asbestos containing material (ACM) also exists within the site building (Redevelopment Cost Estimate, Dec, 2011). The Michigan Department of Environmental Quality (MDEQ) referred the Site to U.S. EPA Region 5 Superfund Division to conduct a removal assessment because of oil and standing water in the former drying machine pits and the presence of various containers on the Site, including approximately 17 55-gallon plastic drums, approximately 60 55-gallon steel drums, six 30-gallon plastic drums, ten 225gallon totes, 24 1-gallon pails, 25 5-gallon buckets, nine (9) boxes of dye, eight (8) bags of polyethylene glycol, and various aerosol cans. The property also includes a former coal storage area which may have resulted in an impact.





Legend
Site Location

0 2,000 4,000
Feet



United States Environmental Protection Agency
ROCKFORD PAPERBOARD
ROCKFORD, KENT COUNTY,
MICHIGAN
TDD No. TO-01-11-05-0012
FIGURE 1
SITE LOCATION MAP

#### 3. SITE ASSESSMENT ACTIVITIES

Site Assessment activities at the Rockford Paperboard Site, including site reconnaissance and sampling activities, are discussed below. U.S. EPA and START performed site assessment activities which included the collection of drum, surface soil and solid samples. MDEQ performed in-field screening of drum contents prior to sample collection.

A site-specific Sampling and Analysis Plan (SAP) was developed for the SA prior to fieldwork. The SAP described the data quality objectives (DQO), sampling strategy, sampling locations, sampling methodology, and analytical procedures used during the SA.

This section summarizes field investigation activities including site reconnaissance (subsection 3.1) and sampling activities (subsection 3.2). Table 1 presents a summary of the field screening results. Table 2 presents a summary of all samples collected and their associated locations. Photographic documentation is provided in Appendix A.

#### 3.1 Site Reconnaissance

On June 13, 2011, U.S. EPA On-Scene Coordinators (OSC), Jeffrey Lippert and Jeffrey Kimble, U.S. EPA Environmental Scientist, Keith Lesniak, and OTIE START members Naren Babu and Elisa Walker mobilized on site and met MDEQ representative Jennifer Wolf and Rockford Paperboard representative Craig Linderman. Upon entering the building, Mr. Linderman noticed recent vandalism in the building and informed local police. A representative from the Kent County Sheriff's Department arrived on site and conducted a site walkthrough and collected fingerprints. U.S. EPA OSC Jeff Kimble conducted a Health and Safety meeting and discussed the SAP and proposed sampling activities.

Prior to conducting the site reconnaissance, START calibrated personal monitoring equipment-RAE Systems ToxiRAE plus Toxic Gas Monitor with a Hydrogen Cyanide (HCN) sensor and MultiRAE® Plus five-gas monitor. The ToxiRAE Plus is a single gas, personal protection monitor with a continuous toxic gas (HCN) concentration display. MultiRAE includes a photoionization detector that measures organic vapors, carbon monoxide (CO) sensor, hydrogen sulfide (H<sub>2</sub>S) sensor, lower explosive limit (LEL) sensor, and oxygen (O<sub>2</sub>) sensor.

U.S. EPA, START, State and Rockford representatives conducted site reconnaissance activities inside the building in Level "D" Personal Protective Equipment (PPE) in accordance with the approved site-specific



HASP. Air monitoring was conducted in the breathing zone throughout the site reconnaissance using a ToxiRAE Plus with HCN sensor and a MultiRAE® plus five-gas monitor.

There are several entrances to the building that were all securely locked. Graffiti was observed on the outside walls of the building. The western portion of the building was historically used for pulping, processing and machining of the paper products. The eastern 44,000 square feet of the facility was constructed more recently (Figure 2). The site reconnaissance began with an entry through the warehouse industrial door on the eastern side of the building. There was no electricity in the building and observations during the site reconnaissance indicated unsafe conditions with collapsed walls, holes (Photo #3) and openings in the floor and wall and open tank areas with caution tape around it. Once inside the warehouse, a large tote was observed. The site reconnaissance continued west from the warehouse and proceeded through the shipping and receiving Area to get to the storage area. There were four poly totes with the signage "NaOH" observed in the storage area (Photo #4). Chemical storage area is located to the west of the storage area, where 62 55-gallon drums were observed. Paperboard machine room is located to the north of the chemical storage area. Long trenches running in an east to west direction were observed in the paperboard machine room (Photo #5). These trenches had sludge material and less than an inch of standing oil/water on top of the sludge material. The chemical lab and maintenance area were located north of the paperboard machine room. Several containers with lab chemicals, including one 1gallon poly can marked as "HCL" were observed in the lab. Inside the trench just south of the maintenance area a "Radiation Hazard" sign was observed (Photo #6). The site reconnaissance continued to the pulping area which is west of the chemical storage area. Large circular pulp tanks are located in the pulping area (Photo #7). A vast amount of dry pulp material was observed to be sticking to the roof and in the basement throughout the pulping area. The new and old boiler rooms are located west of the pulping area. Potential fallen asbestos containing material (ACM) was observed in the new boiler room. One of the staircases in the pulping area leading to the basement was not in working condition. Abandoned equipment, empty drums and buckets were observed throughout the building. A clarifier was located outside the building southwest of the boiler rooms. A former coal storage area is located directly west of and behind the boiler rooms, just north of the clarifier. Dark soil was observed in the former coal storage area. Graffiti on the walls and trash throughout the building confirmed that vandalism occurred inside the building (Photo #8).

An inventory conducted throughout the facility indicated that there were about 30 small containers, one cylinder, one tote of solvent, three pallets of CR-800 Titanium Dioxide (Manufactured by Kerr McGee), one pallet Polyvinyl Alcohol, one tote containing a mix of Cyclohexyamine [108-91-8] and NN Diethylsnolsmine [100-37-8]), 11 drums, two 1,000 gallon tanks, 10-300 gallon totes, and seven bags of



Polyethylene glycol 3350 granules present in the other areas of the building excluding the chemical storage area and the chemical lab.

#### 3.2 Sampling Activities

After the site reconnaissance and container inventory, sampling activities were conducted. Samples were collected for on-site field screening and for off-site chemical analysis at a commercial laboratory. All drum samples were collected using dedicated glass drum thieves and directly transferred into lab-supplied clean sample jars.

#### 3.2.1 Field Screening Tests

U.S. EPA collected samples from inside the building in Level "B" PPE for field screening tests. A total of five drum samples were collected for field screening with Ahura Scientific TruDefender and FirstDefender instruments. The TruDefender and FirstDefender instruments analyze the sample and compare its constituent chemicals and composition to a database of known products and identify likely products or chemical compositions. Drums were opened using a bung wrench. Samples for field screening were collected in dedicated 4-milliliter (mL) glass vials from drums RP-DRUM-01, RP-DRUM-02, RP-DRUM-03, RP-DRUM-04, and RP-DRUM-05. The MultiRAE and ToxiRAE with hydrogen cyanide sensor instruments were used throughout sampling activities for air monitoring. During drum opening and sampling, no breathing zone air monitoring readings above background were detected on either of the devices. The vials were screened outside the building by Ms.Wolf of MDEQ using FirstDefender and TruDefender instruments. pH test paper strips were used to obtain the pH values of the liquid drum samples. Results of the field screening tests are presented in Table 1.

TruDefender field screening identified RP-DRUM-01 sample as water and RP-DRUM-02 sample as CAS; 110-91-8/ UN: 2084/C4H9ON/Morpholine, which is used as an additive for pH adjustments in several industries. The FirstDefender field screening identified RP-DRUM-03 sample as a mixture of 5% Ethylene glycol, 3% Cyclohexylactylone, and 80% water and RP-DRUM-04 sample as a mixture of 83% Water, 6% Vanadium (V) oxyfluoride, and 2% N, N-Diglycidyl-4-glycidyloxy aniline. Sample RP-DRUM-05 did not have any match with the database listed products in either TruDefender or the FirstDefender field screening tests.



# Table 1 Field Screening Results TruDefender and First Defender Analysis Rockford Paperboard Assessment Rockford, Michigan

Rockioi di Micingan								
Drum	TruDefender	FirstDefender						
	***	27.76						
RP-DRUM-01	Water	No Match						
RP-DRUM-02	CAS:110-91-8/	No Match						
	UN:2084/C4H9ON							
RP-DRUM-03	No Match	Ethylene glycol-5%						
		Cyclohexylactylone-3%						
		Water-80%						
RP-DRUM-04	No Match	Water-83%						
		Vanadium(V)oxyfluoride-6%						
		N,N-Diglycidyl-4-glycidyloxy aniline-2%						
RP-DRUM-05	No Match	No Match						

#### Notes:

Drum- Identification name given for drum samples

No Match- The instruments could not identify the sample or it was identified by either the TruDefender or FirstDefender

MDEQ representative (J. Wolf) conducted the screening

TruDefender- Fourier Transform Infrared (FTIR) System used to analyze and identify unknown chemicals FirstDefender- Thermo Scientific instrument for rapid, accurate identification of unknown chemicals in the field

Samples were collected on June 13, 2011 under START contract EP-S5-10-10.



#### 3.2.2 Analytical Sampling

U.S. EPA and START evaluated the field screening results and selected potential drums and solid material for sampling and laboratory analysis. A total of four solid samples and seven liquid samples were collected. Solid sampling was conducted in Level "D" PPE and liquid sampling was conducted in level "B" PPE. Air monitoring was conducted using MultiRAE and ToxiRAE with HCN during sampling activities.

A sample of potential ACM, RP-AS-01, was collected from the basement level of the New Boiler Room (Photo #9). A five-point composite sample, RP-SOLID-01, was collected from the dark soil in the former coal storage area. Two solid samples, RP-SOLID-02 and RP-SOLID-03, were collected from the trenches located in the paperboard machine room. A solid sample, RP-SOLID-04, was collected from the dry pulp material present at the basement level of the pulping area and new boiler room (Photo #10). Sample locations, descriptions and laboratory analyses for the solid samples are summarized in Table 2.

Liquid samples were collected from RP-DRUM-01, RP-DRUM-02, RP-DRUM-03, RP-DRUM-04, RP-DRUM-05, RP-DRUM-06, and RP-DRUM-07. Samples RP-DRUM-01, -02, -03, -04, and -05 were collected from drums stored in the chemical storage area and RP-DRUM-06 was collected from the concentrated hydrochloric acid can in the lab. Prior to sampling, fumes were noted upon opening the cap of the acid can. During the collection of liquid sample RP-DRUM-07 in the warehouse, the MultiRAE peaked at 250 parts per million (ppm) for VOCs, 30ppm for CO and 10% for O2. A hissing noise was noted upon opening the bung of the tote, probably due to the contents inside the tote being under pressure. During all other sampling activities no readings above background were detected on the MultiRAE or ToxiRAE. Sample locations, descriptions and laboratory analyses for liquid samples are summarized in Table 2.

START prepared the sample jars with labels, completed the chain of custody and placed all samples on ice. START secured the samples inside a cooler for transportation. Samples were delivered to TestAmerica in University Park, IL on June 15, 2011.



## Table 2 **Sampling Summary Rockford Paperboard Site Assessment** Rockford, Michigan

Sample ID Sample Description Laboratory Analyses							
Sample 1D	Sample Description	Laboratory Analyses					
DD 4 G 01	Bi Caralla GM 1						
RP-AS-01	Pieces of potential ACM in the	Asbestos					
	basement level the new boiler room						
	(Photo# 9)						
RP-SOLID-01	Composite soil sample from the former	Total &TCLP VOCs, Total &TCLP					
	coal storage area west of the old boiler	SVOCs, Total &TCLP MI 10 Metals					
	room and north of the clarifier						
RP-SOLID-02	Sludge material collected from trench	Total &TCLP VOCs, Total &TCLP					
	(possible rotten pulp) in the Paperboard	SVOCs, Total &TCLP MI 10 Metals,					
	Machine Room	and PCBs					
RP-SOLID-03	Dark sludge with purple color to it	Total &TCLP VOCs, Total &TCLP					
	collected from trench in the Paperboard	SVOCs, Total &TCLP MI 10 Metals,					
	Machine Room	and PCBs					
RP-SOLID-04	Pieces of material in room in the	Total &TCLP VOCs, Total &TCLP					
	basement level the new boiler room and	SVOCs, Total &TCLP MI 10 Metals					
	west of the Pulping Area (Photo# 10)						
RP-DRUM-01	Liquid Sample from Drum #01 in	pH					
	drum/tank area						
RP-DRUM-02	Liquid Sample from Drum #02 in	pH, flashpoint					
	drum/tank area						
RP-DRUM-03	Liquid Sample from Drum #03 in	pH					
	drum/tank area						
RP-DRUM-04	Liquid Sample from Drum #04 in	pH, flashpoint					
	drum/tank area						
RP-DRUM-05	Liquid Sample from Drum #05 in	Total & TCLP VOCs, pH, flashpoint					
	drum/tank area						
RP-DRUM-06	Liquid Sample from poly can labeled	pH					
	HCL from the Chemical Lab						
RP-DRUM-07	Liquid Sample from poly tote in the	Total VOCs, pH, and flashpoint					
	Warehouse						

#### Notes:

VOCs volatile organic compounds


semi-volatile organic compounds SVOCs -


Toxic Characteristic Leaching Procedure TCLP -


Sample ID- identification names given for samples
Samples were collected on June 13, 2011 under START contract EP-S5-10-10. Analyses were conducted by


TestAmerica Laboratories, Inc. under TDD No: TO-01-11-05-0012

















#### 4. SAMPLE ANALYTICAL RESULTS

START reviewed the sample analytical data and supporting quality assurance/quality control (QA/QC) data provided by TestAmerica Laboratories. The validated analytical data package is included in Appendix B. Based on START's data validation, the data are acceptable for use as qualified.

Analytical results of the drum samples that were above the method detection level are shown in Table 3. The results in the tables were compared against values listed in 40 Code of Federal Regulations (CFR) Section 261.22-261.24. Analytical results for the solid samples collected during the site assessment are shown in Table 4.

Sample RP-DRUM-01 result indicated a pH value of 13.7 standard units (SU), while sample RP-DRUM-07 had a pH value of 12.6 SU. These samples exceed the Hazardous Characterization criteria for corrosivity of >12.5 pH per 40 CFR Section 261.22 regulations. RP-DRUM-01 and RP-DRUM-07 are considered strong bases. pH results for RP-DRUM-02 through 06 were all between 2 and 12.5 SU and did not exceed the Hazardous Characterization Criteria for Corrosivity. The pH of the acid sample RP-DRUM-06, is reported as "non-detect" because the pH of the sample was lower (more acidic) than that the meter could accurately measure. RP-DRUM-06 is corrosive acid per 40 CFR Section 2621.22 regulations

Sample RP-DRUM-05 and RP-DRUM-07 had a flashpoint of 140 degrees Fahrenheit (°F). Flashpoint results for drum samples RP-DRUM-02 and RP-DRUM-04 are both greater than 176 °F. Liquids with flashpoints below 140 degrees are characterized as "ignitable" according to 40CFR section 261.21. In addition to this, drum sample RP-DRUM-07 indicated an acetone concentration of 200 mg/L.

Soil sample RP-SOLID-01, collected from the former coal storage area and Sludge samples RP-SOLID-02 and RP-SOLID-03, collected from the trenches in the paperboard machine room had several detected VOCs, SVOCs and metals but none of the TCLP results exceeded the 40 CFR Section 261.24 regulatory limits for defining hazardous characteristics. Analytical results did not indicate any **p**olychlorinated biphenyls (PCBs) were detected in the sludge samples.

The dry pulp sample, RP-SOLID-04 had several detected results for SVOCs and metals but none of the TCLP results exceeded the 40 CFR Section 261.24 regulatory limits for defining hazardous characteristics.



#### Table 3 Drum Sample Analytical Results Rockford Paperboard Site Assessment Rockford, Michigan

ANALYTE/ PARAMETER	40 CFR Section 261 Regulatory Limit <sup>1</sup>	RP- DRUM-01	RP-DRUM- 02	RP-DRUM- 03	RP-DRUM- 04	RP- DRUM-05	RP-DRUM- 06	RP-DRUM-07
pH (SU)	<2 or >12.5	13.7 HF	11.0 HF	12.3 HF	8.46 HF	11.8 HF	<2	12.6 HF
Flashpoint (*F)	<140	NA	>176	NA	>176	140	NA	140

- 111211 <b>F</b> 21111 ( - )							
ANALYTE/ PARAMETER	RP-DRUM-05	RP-DRUM-07					
Total VOCs (mg/L)							
Acetone	0.14	220					
Benzene	ND	0.068					
Ethylbenzene	0.03	0.57					
Isopropylbenzene	ND	0.37					
Methyl tert-butyl ether	ND	0.17					
Methylene Chloride	ND	0.66					
N-Propylbenzene	0.0059 J	ND					
1,2,3-Trichlorobenzene	0.011	ND					
1,2,4-Trimethylbenzene	0.047	ND					
1,3,5-Trimethylbenzene	0.015	ND					
o-Xylene	0.1	ND					

#### Notes:

Hazardous Waste Characterization Criteria according to 40 CFR Sections 261.21-261.24

SU - standard units

VOCs - volatile organic compounds

°F - degrees Fahrenheit

mg/L - milligrams per liter

HF- Field parameter with a holding time of 15 minutes

J - result less than the RL but greater than or equal to the MDL and the concentration is an approximate value

The pH of the sample, RP-DRUM-06, was lower (more acidic) than the meter could accurately measure and is reported as <2 SU.

 $NA-\quad \ \ analyte\ not\ analyzed$ 

ND - analyte not detected above the laboratory method detection limit

NL - Not listed

Only detected compounds are in tables

Samples were collected on June 13, 2011 under START contract EP-S5-10-10.

Analyses were conducted by TestAmerica Laboratories, Inc. under TDD No: TO-01-11-05-0012



# Table 4 Analytical Results of Solid Samples Rockford Paperboard Site Assessment Rockford, Michigan

ANALYTE   RP-SOLID-01   RP-SOLID-02   RP-SOLID-03   RP-SOLID-04									
		RP-SOLID-01		RP-SULID-02		Kr-SULID-03		KI-SULID-04	
Total VOCs (mg/Kg) Acetone		ND		ND		NID		0.056	
Ethylbenzene	0.0094 J		ND ND		ND ND		0.056 ND		
Toluene	0.0094 J 0.034		ND ND		ND ND				
trans-1,2-Dichloroethe			ND ND		ND 0.073		ND ND		
	ene	0.16 0.025							
Trichloroethene				ND ND		ND ND		ND	
1,2,4-Trimethylbenzer	ne		04 J					ND	
Methylene Chloride			.38	ND		ND		ND	
m&p-Xylene			055 043	ND		ND		ND	
o-Xylene	<u> </u>	0.0	043	0.014 J		ND		ND	
Total SVOCs (mg/Kg)	)	0.044		MD		ND.		ND	
Acenaphthylene				ND		ND 2.0 I		ND ND	
Anthracene			.12	ND		3.0 J			
Benzo[a]anthracene			.36	ND			1 J	N	
Benzo[a]pyrene			.29	ND		ND		ND	
Benzo[b]fluoranthene			.38	ND		ND		ND	
Benzo[g,h,i]perylene			.19 .16	ND ND		ND ND		ND	
Benzo[k]fluoranthene	1 . 4 .			ND		ND		ND 2.0	
Bis(2-ethylhexyl) phth Butyl benzyl phthalate		0.089 J		24 J		ND ND		2.0	
Carbazole	2	ND 0.071 J		ND ND		ND ND		0.94 ND	
Chrysene		0.40		ND ND		ND ND		ND ND	
Dibenz(a,h)anthracene		0.057		ND ND		ND ND		ND ND	
Dibenzofuran	<del>-</del>	0.057		ND ND		ND ND		ND ND	
Fluoranthene	0.25		ND ND		4.3 J		0.15		
Fluorene		0.060		ND ND		ND		ND	
Indeno[1,2,3-cd]pyren	0.13		ND		ND ND		ND		
2-Methylnaphthalene	ic	0.89		ND		ND		ND	
Naphthalene Naphthalene		0.57		ND		ND		ND	
N-Nitrosodiphenylam	ine	ND		ND		ND		0.19 J	
Phenanthrene	0.75		ND		9.4		0.27		
Pyrene		0.73		6.1 J		10		0.27	
1 yrene	Regulatory	0.58		0.13		10		0.51	
	Action								
ANALYTE	Level	RP-SOLID-01		RP-SOLID-02		RP-SOLID-03		RP-SOLID-04	
Metals		Total	TCLP	Total	TCLP	Total	TCLP	Total	TCLP
Arsenic	5.00	12	ND	9.9	0.018 J	9.6	ND	0.48 J	ND
Barium	100.00	48	0.25 J	360	0.12 J	200	0.075 J	36	0.5
	1.00		NID		NID		0.0028		0.0055
Cadmium	1.00	0.25	ND	1.4	ND	2.2	J	0.21 J	0.0055
Chromium	5.00	11 B	ND	27 B	ND	32 B	ND	15 B	0.052
	NII		0.011 J		0.07 D		0.14 D		0.71
Copper	NL	29	В	250	0.07 B	280	0.14 B	82	0.71
5.00			0.0081		Λ 11		0.22		0.04.1
Lead		43	J	390	0.11	1600	0.32	15	0.04 J
Mercury -		0.078	-	0.036	-	0.053		0.11	
Selenium	-	0.49 J	-	ND	-	0.52 J		0.39 J	
Silver	-	ND	-	0.33 J	-	0.43 J		0.13 J	
Zinc NL		50	0.17	460	0.6	260	0.77	65	1



#### Notes:

VOCs - volatile organic compounds

SVOCs -semi-volatile organic compounds

mg/L- milligram per liters (TCLP)

mg/Kg - milligram per kilogram (Total)

J - result less than the RL but greater than or equal to the MDL and the concentration is an approximate value

NA- not analyzed

ND – analyte not detected above the laboratory method detection limit

TCLP - Toxic Characteristic Leaching Procedure

Only detected compounds are in tables

Regulatory Action Level is in compliance with 40 CFR Section 261.21-24 Regulatory Limit

Samples were collected on June 13, 2011 under START contract EP-S5-10-10.

Analyses were conducted by TestAmerica Laboratories, Inc. under TDD No: TO-01-11-05-0012



#### 5. POTENTIAL SITE RELATED THREATS

Threats posed by the Site were evaluated in accordance with National Contingency Plan (NCP) criteria for initiating a removal action listed under Title 40 of the CFR, Section 300.415(b) (2). Paragraph (b) (2) of 40 CFR Section 300.415 lists factors to be considered when determining the appropriateness of a potential removal action at a Site. Potential site-related threats to human health and the environment were evaluated based on the criteria listed in 40 CFR, Sections 261.20 through 261.24. Factors that are applicable to the Site are discussed below.

Actual or potential exposure of nearby human populations, animals, or the food chain to hazardous substances or pollutants or contaminants

Drums, containers and totes with no secondary containment are located inside the Site building. In addition, one of the drum samples had a pH greater than 12.45 SUs, indicating corrosivity. The Site showed signs of trespassing and vandalism. Overall, the potential for exposure to potentially hazardous substances stored at the Site is high, especially considering that the on-site building is no longer occupied.

The presence of hazardous material poses a threat to nearby residents through direct exposure since the Site has signs of vandalism inside the building.

#### Actual or potential contamination of drinking water supplies or sensitive ecosystems

The Rogue River runs behind the Site. It is possible that the contents of drums, totes, or buckets can be introduced into the water by trespassers. Fire or explosion can also cause a release into the water.

# Hazardous substances or pollutants or contaminants in drums, barrels, tanks, or other bulk storage containers that may pose a threat of release

RP-DRUM-01 and RP-DRUM- have pH values of 13.7 and 12.6, respectively. Both samples are strong bases and exceed the Title 40 CFR Section 261.22 pH criteria of >12.5 for hazardous corrosive characterization. There are four poly totes in the storage area with sodium hydroxide labels, which is a strong base. Additionally, the poly can in the chemical lab contain concentrated hydrochloric acid. Vandalism could lead to tipping over of the drums and containers releasing the contents of the drum inside of the building. In case of fire, the material stored in drums inside the Site building could result in the release of toxic gases causing potential exposure to nearby residents. These drums pose a potential threat of release to the environment.



#### Threat of fire or explosion

RP-DRUM-05 and RP-DRUM-07 have a flashpoint of 140 °F. Contents of both these drums are on the borderline to the limit that is considered ignitable according to 40 CFR 261. These drums and several other similar drums pose a high threat of fire or explosion based on the flammable nature of the drum contents, the unoccupied status of the building, and the evidence of trespassing and vandalism observed during the site assessment.

#### The availability of other appropriate federal or state response mechanisms to respond to the release

MDEQ requested the assistance of U.S. EPA Region 5 Emergency Response Branch to help evaluate and mitigate a possible threat posed by the Rockford Paperboard Site. This request was made to U.S. EPA since MDEQ does not have appropriate state response mechanisms or resources to respond.



#### 6. SUMMARY

On June 13, 2011, U.S. EPA, MDEQ and START conducted site assessment activities at the Rockford Paperboard Site in Rockford, Michigan. Field screening tests were conducted to analyze several drums found in the building prior to sampling activities. During sampling activities, liquid drum and sludge trench and solid samples were collected and submitted for pH, flashpoint, total VOCs and SVOCs, total metals, and TCLP metals analyses.

Sample analytical results were evaluated against the criteria of characteristics of hazardous waste (40 CFR, Sections 261.20 through 261.24). Drums and totes containing highly basic compounds, acidic compounds and ignitable materials were observed in the Site building and pose a threat of release. Clear signs of trespassing and vandalism are also present inside and outside the Site building. Thus, conditions exist at the site that support a removal action be conducted to abate threats to human health and the environment.



# 7. REFERENCES

 Dixon Environmental Consulting, Inc., 2011. Redevelopment Cost Estimate for Rockford Paperboard, Inc. Property



# APPENDIX A

# PHOTOGRAPHIC LOG

(6 Pages)



**Photograph No.:** 1 **Photographer:** Naren Babu **Orientation:** Looking East **TDD Number:** TO-01-11-05-0012 **Contract:** EP-S5-10-10, OTIE **Date:** June 13, 2011

Site Name & Location: Rockford Paperboard Site, Rockford, Michigan.

**Subject:** Front view of the facility.



Photograph No.: 2 Photographer: Naren Babu Orientation: Looking South TDD Number: TO-01-11-05-0012 Contract: EP-S5-10-10, OTIE Date: June 13, 2011

Site Name & Location: Rockford Paperboard Site, Rockford, Michigan.

**Subject:** View of the fence on the west side of the building.



Photograph No.: 3Photographer: Naren BabuOrientation: Looking DownTDD Number: TO-01-11-05-0012Contract: EP-S5-10-10, OTIEDate: June 13, 2011

**Site Name & Location:** Rockford Paperboard Site, Rockford, Michigan.

Subject: View of holes in facility floor.



Photograph No.: 4 Photographer: Naren Babu Orientation: Looking Down TDD Number: TO-01-11-05-0012 Contract: EP-S5-10-10, OTIE Date: June 13, 2011

**Site Name & Location:** Rockford Paperboard Site, Rockford, Michigan. **Subject:** View of Sodium Hydroxide (NaOH) tote in the Storage Area.



Photograph No.: 5Photographer: Naren BabuOrientation: Looking DownTDD Number: TO-01-11-05-0012Contract: EP-S5-10-10, OTIEDate: June 13, 2011

Site Name & Location: Rockford Paperboard Site, Rockford, Michigan.

Subject: View of the trench inside the Paperboard Machine Room



Photograph No.: 6 Photographer: Naren Babu Orientation: Looking Down TDD Number: TO-01-11-05-0012 Contract: EP-S5-10-10, OTIE Date: June 13, 2011

**Site Name & Location:** Rockford Paperboard Site, Rockford, Michigan. **Subject:** View of equipment in trench and "Radiation Hazard" sign.



Site Name & Location: Rockford Paperboard Site, Rockford, Michigan.

Subject: Outside and inside View of pulp tank.



Photograph No.: 8 Photographer: Naren Babu Orientation: Looking West TDD Number: TO-01-11-05-0012 Contract: EP-S5-10-10, OTIE Date: June 13, 2011

Site Name & Location: Rockford Paperboard Site, Rockford, Michigan.

**Subject:** View of graffiti inside the site building.



**Photograph No.:** 9 **Photographer:** Elisa Walker **Orientation:** Looking North

Site Name & Location: Rockford Paperboard Site, Rockford, Michigan.

**Subject:** View of area where suspected ACM sample, RP-AS-01, was collected from the New boiler room.



Photograph No.: 10 Photographer: Naren Babu Orientation: Looking Down

Site Name & Location: Rockford Paperboard Site, Rockford, Michigan.

**Subject:** View of dry pulp material collected from the basement level of the New boiler room and west of the pulping area for sample, RP-SOLID-04.



Photograph No.: 11 Photographer: Naren Babu Orientation: Looking Southwest

Site Name & Location: Rockford Paperboard Site, Rockford, Michigan.

**Subject:** View of the Rogue River behind the building.



Photograph No.: 12 Photographer: Naren Babu Orientation: Looking North TDD Number: TO-01-11-05-0012 Contract: EP-S5-10-10, OTIE Date: June 13, 2011

Site Name & Location: Rockford Paperboard Site, Rockford, Michigan.

**Subject:** View of the graffiti outside the building.

# APPENDIX B

# VALIDATED LABORATORY ANALYTICAL RESULTS

**(81 Pages)** 

#### **MEMORANDUM**

**Date:** July 15, 2011

**To:** Naren Babu, Project Manager, OTIE

longe A. Lanchez

Superfund Technical Assessment and Response Team (START) for Region 5

Prepared by: Jorge A. Sanchez, Senior Project Chemist/Project Manager

QA/QC

Keely Meadows, START Senior Engineer

Concurrence

by:

**Subject:** Data Validation

Rockford Package Rockford, MI

Laboratory: TestAmerica, Chicago, IL. Laboratory Certification ID#: 100201

Lab SDG# 500-35461-1: Analyses of six (6) solid/aqueous samples for total and TCLP volatile organic compounds (VOCs). Five (5) solid/aqueous samples for total and TCLP semi volatile compounds (SVOCs). Four (4) solid samples for total and TCLP metals/mercury. Two (2) solid samples for polychlorinated biphenyls (PCBs). Seven (7) aqueous samples for pH. Four (4) aqueous samples for flashpoint. Four (4) solid samples for percent moisture and percent solids.

Laboratory: EMLab P&K, Cherry Hill, NJ.

Laboratory ID: 795827

Lab Project# 50005626, Lab ID-version ID# 3524674-1: Analyses of one (1) multicolored semi-fibrous material sample for asbestos.

#### 1.0 INTRODUCTION

START validated six (6) solid/aqueous samples for total and TCLP volatile organic compounds (VOCs), five (5) solid/aqueous samples for total and TCLP semi volatiles compounds (SVOCs), four (4) solid sample for total and TCLP metals/mercury analyses, two (2) solid samples for polychlorinated biphenyls (PCBs), seven (7) aqueous samples for pH, four (4) aqueous samples for flashpoint and four (4) solid samples for percent moisture and percent solids. A sample was submitted to EMLab P&K in Cherry Hill, NJ for asbestos. All samples were collected on June 13, 2011.

Laboratory data were validated using guidelines set forth in the U.S. EPA Contract Laboratory Program National Functional Guidelines for Organic Data Review (EPA540/R-99/008, October 1999), U.S. EPA Contract Laboratory Program National Functional Guidelines for Inorganic Data Review (EPA 540/R-940/R

Data Validation for Rockford Package Page 2

94/013, February, 1994), and applicable methodologies. The purpose of the chemical data quality evaluation process is to assess the usability of data for the project decision-making process.

Organic data validation consisted of a review of the following QC audits:

- Chain of custody and sample receipt forms review
- Sample preservation and holding time
- Blank results
- Surrogate recoveries
- Internal Standards areas and retention times
- Laboratory Control Sample (LCS) recovery results

Inorganic data validation consisted of a review of the following QC audits:

- Chain of custody and sample receipt forms review
- Sample preservation and holding time
- Blank results
- Laboratory Control Sample (LCS) recovery results

Section 2.0 of this memorandum discusses the results of organic data validation. Section 3.0 of this memorandum discusses the results of inorganic data validation. Section 4.0 presents an overall assessment of the data. The attachment to this memorandum contains the laboratory reporting forms as well as START's handwritten data qualifications where warranted. "Q" qualifiers will replace the following laboratory qualifiers in this report: asterisk (\*), carrot top (^), X, and P.

#### 2.0 ORGANIC DATA VALIDATION RESULTS

The Results of START's organic data validation are summarized below by QC audit review. After the START project staff received the data packages, they were inventoried for completeness and then reviewed according to matrix-specific protocols and data quality objectives established for the project.

# **2.1** TOTAL AND TCLP VOLATILE ORGANIC COMPOUNDS (VOCs) SAMPLES by GC/MS METHOD 8260B (Lab SDG# 500-35461-1).

#### 2.1.1 SAMPLE HANDLING

Chain of custody documentation and sample receipt forms were reviewed to ensure requested analyses were performed and that samples arrived at the laboratory intact. All samples were received with no discrepancies noted by the lab.

#### 2.1.2 SAMPLE PRESERVATION AND HOLDING TIME

Solid and aqueous samples were analyzed within holding time criteria. No discrepancies were noted.

#### 2.1.3 BLANK RESULTS

The purpose of laboratory (or field) blank analysis is to determine the existence and magnitude of contamination resulting from laboratory (or field) activities. Laboratory method blank samples (MB-500-

Data Validation for Rockford Package Page 3

116824/4, LB3-500-116812/1-A, MB-500-117160/7, MB-500-117161/7, LB-500-117051/1-A, MB-500-117181/4, and MB-500-117281/8) were run with this SDG.

No method blank detects were noted.

#### 2.1.4 SURROGATE STANDARD RECOVERY

Laboratory performance on individual samples is established by means of fortifying each sample with surrogate compounds (System Monitoring Compounds). Surrogate spike compounds included dibromofluoromethane, 1,2-dichloroethane-d4, toluene-d8 and 4-bromofluorobenzene.

Surrogate recoveries for the following samples were outside control limits: RP-Drum-05 (500-35461-9), RP-Drum-07 (500-35461-11). Evidence of matrix interference is present (pH=11). The samples were reanalyzed with similar results. It has been found that a basic sample interfered with surrogate recoveries.

Discrepancies were noted.

#### 2.1.5 INTERNAL STANDARD AREAS AND RETENTION TIMES

Internal standard areas and retention times were within QC limits. Internal standards used for this batch are: pentafluorobenzene, 1, 4-difluorobenzene, chlorobenzene-d5 and 1, 4-dichlorobenzene-d4.

No discrepancies were noted.

#### 2.1.6 MS/MSD RECOVERY RESULTS

Data for MS/MSDs are generated to determine long-term precision and accuracy of the analytical method on various matrices and to demonstrate acceptable compound recovery by the laboratory at the time of sample analysis.

However, MS/MSD was not run on this SDG due to the nature of the waste stream samples.

#### 2.1.7 LCS/LCSD RECOVERY RESULTS

Data for the LCS/LCSD is generated to provide information on the accuracy of the analytical method and on the laboratory performance. The LCS is fortified with the full list of VOCs and analyzed with each batch of samples. The LCS accuracy performance is measured by Percent Recovery (%R). Laboratory control samples (LCS-500-116824/5, LCS-500-117161/5, LCS-500-117181/5 and LCS-500-11728/5) were run with this SDG. No deficiencies were noted.

Deficiencies were noted for the solid matrix laboratory control sample (LCS) for batch 117160. Dichlorodifluoromethane and 1,2,3-Trichlorobenzene were outside the in-house generated QC limits. Samples associated with this batch number 117160 were "Q" flagged due to the out of control QC sample. Sample numbers 500-35461-2, 500-35461-3 and 500-35461-4 were not affected by these deficiencies due to no hits reported for the out of control compounds.

#### 2.1.8 GENERAL LABORATORY OBSERVATIONS

No additional laboratory observations were noted for VOC analysis of air.

# **2.2** TOTAL AND TCLP SEMIVOLATILE ORGANIC COMPOUNDS (SVOCs) SAMPLES by GC/MS METHOD 8270C (Lab SDG# 500-35461-1).

#### 2.2.1 SAMPLE HANDLING

Chain of custody documentation and sample receipt forms were reviewed to ensure requested analyses were performed and that samples arrived at the laboratory intact. All samples were received with no discrepancies noted by the lab.

#### 2.2.2 SAMPLE PRESERVATION AND HOLDING TIME

Solid and aqueous samples were analyzed within holding time criteria. No discrepancies were noted.

#### 2.2.3 BLANK RESULTS

The purpose of laboratory (or field) blank analysis is to determine the existence and magnitude of contamination resulting from laboratory (or field) activities. Laboratory method blank samples MB-500-116744/1-A, MB-500-116969/1-A, LB-500-116867/1-D, LB2-500-116869/1-D, MB-500-116993/1-A and LB3-500-116807/1-E were analyzed for this SDG.

No method blank detects were noted.

#### **2.2.4** SURROGATE STANDARD RECOVERY

Laboratory performance on individual samples is established by means of fortifying each sample with surrogate compounds (System Monitoring Compounds). Surrogate spike compounds included 2-fluorophenol, phenol-d5, Nitrobenzene-d5, 2-fluorobiphenyl, 2,4,6-tribromophenol and terphenyl-d14.

The following discrepancies were noted; surrogate recovery for 2-fluorophenol in the following sample was biased low 17% (20%-100%): RP-Solid-04 (500-35461-12). All recoveries were within limits.

In addition, due to the level of dilution required for the following samples, surrogate recoveries were not reported: RP-Drum-07 (500-35461-11), RP-Solid-02 (500-35461-3), RP-Solid-03 (500-35461-4).

No further action was taken due to the out of control parameters.

#### 2.2.5 INTERNAL STANDARD AREAS AND RETENTION TIMES

Internal standard areas and retention times were within QC limits. Internal standards used for this batch are: 1,4-dichlorobenzene-d4, naphthalene-d8, acenaphthene-d10, phenanthrene-d10, chrysene-d12 and perylene-d12.

The internal standard (STD40-500-115121/9) retention times for samples and CCV's were outside the +/-0.5 minutes of acceptance from the mid-point of the initial calibration. The samples and CCV's were within +/- 0.5 minutes from the daily calibration verification. No corrective action was required per TAL Chicago SOP.

Data Validation for Rockford Package Page 5

The internal standard response was outside of acceptance limits for the following sample: RP-Solid-04 (500-35461-12). The sample shows evidence of matrix interference. No further action was taken.

Discrepancies were noted.

#### 2.2.6 MS/MSD RECOVERY RESULTS

Data for MS/MSDs are generated to determine long-term precision and accuracy of the analytical method on various matrices and to demonstrate acceptable compound recovery by the laboratory at the time of sample analysis.

However, MS/MSD was not run on this SDG due to the nature of the waste stream samples.

#### 2.2.7 LCS/LCSD RECOVERY RESULTS

Data for the LCS/LCSD is generated to provide information on the accuracy of the analytical method and on the laboratory performance. The LCS is fortified with the full list of SVOCs and analyzed with each batch of samples. The LCS accuracy performance is measured by Percent Recovery (%R). An LCS (LCS-500-116744/2-A) was run with batch number 116744. An LCS/LSCD (LCS-500-116969/2-A/LCSD-500-116969/3-A) was run with batch number 116969. An LCS (LCS-500-116993/2-A) was run with batch number 116993.

The %RPD of the laboratory control sample (LCS) and laboratory control standard duplicate (LCSD) for preparation batch 116969 exceeded control limits (20%) for the following analytes: benzoic acid at 108%; pentachlorophenol at 25%; and benzo[k]fluoranthene at 23%. All recoveries were within limits. No further action was taken.

No deficiencies were noted for batch numbers 116744 and 116993.

#### **2.2.8** GENERAL LABORATORY OBSERVATIONS

The following samples were diluted due to the abundance of non-target analytes: RP-Drum-07 (500-35461-11), RP-Solid-02 (500-35461-3) and RP-Solid-03 (500-35461-4). Elevated reporting limits (RLs) were provided. All diluted samples were "D" flagged by the laboratory.

The ICV (Mix1) analyzed on instrument number MS20 on (06/01/11 at 17:11 hours) had benzoic acid at 28%, high. The ICV (Mix2) analyzed on instrument number MS21 on (06/14/11 at 19:02 hours) had pyridine at 49.1%, high. The CCV's were in control for these analytes. All affected samples were "Q" flagged for out of quality control criteria.

# 2.3 POLYCHLORINATED BYPHENYLS (PCBS) BY GAS CHROMATOGRAPHY (GC) BY METHOD 8082 (Lab SDG# 500-35461-1)

#### 2.3.1 SAMPLE HANDLING

Chain of custody documentation and sample receipt forms were reviewed to ensure requested analyses were performed and that samples arrived at the laboratory intact. An additional sample was received that was not indicated on the COC. The laboratory added the sample to the COC and confirmed with the

Data Validation for Rockford Package Page 6

client which analyses were to be analyzed. The laboratory was subsequently provided an additional COC via email from the client.

All samples were received with no discrepancies noted by the lab.

#### 2.3.2 SAMPLE PRESERVATION AND HOLDING TIME

All samples were analyzed within holding time criteria. No discrepancies were noted.

#### 2.3.3 BLANK RESULTS

The purpose of laboratory (or field) blank analysis is to determine the existence and magnitude of contamination resulting from laboratory (or field) activities. A laboratory method blank sample, MB-500-116749/1-A, was run with batch number 116749.

No method blank detects were noted.

#### **2.3.4** SURROGATE STANDARD RECOVERY

Laboratory performance on individual samples is established by means of fortifying each sample with surrogate compounds (System Monitoring Compounds). Surrogate spike compounds included tetrachloro-m-xylene and DCB decachlorobiphenyl.

Surrogate recovery for the following samples exceeded control limits: RP-Solid-02 (500-35461-3), RP-Solid-03 (500-35461-4). Evidence of matrix interference is present; therefore, re-extraction and/or reanalysis were not performed. The affected samples were "Q" flagged due to the out of quality control parameter.

No other discrepancies were noted.

#### 2.3.5 MS/MSD RECOVERY RESULTS

Data for MS/MSDs are generated to determine long-term precision and accuracy of the analytical method on various matrices and to demonstrate acceptable compound recovery by the laboratory at the time of sample analysis.

However, MS/MSD was not run on this SDG due to the nature of the waste stream samples.

#### 2.3.6 LCS/LCSD RECOVERY RESULTS

Data for the LCS/LCSD is generated to provide information on the accuracy of the analytical method and on the laboratory performance. The LCS is fortified with the full list of PCBs and analyzed with each batch of samples. The LCS accuracy performance is measured by Percent Recovery (%R). An LCS (LCS-500-116749/3-A) was run with for batch number 116749.

No other discrepancies were noted.

Data Validation for Rockford Package Page 7

#### 2.3.7 GENERAL LABORATORY OBSERVATIONS

The grand mean exception, as outlined in EPA Method 8000B, was applied to continuing calibration verification (CCV) standards. This rule states that when one of more compounds in the CCV fail to meet acceptance criteria, the data may be reported if the average %D (the grand mean) of all the compounds in the CCV is less than or equal to 15%D. The following compounds are affected: AR1260.

The following samples required a mercury clean-up to reduce matrix interferences caused by sulfur: RP-Solid-02 (500-35461-3) and RP-Solid-03 (500-35461-4).

The %RPD between the primary and confirmation column/detector is >40%. The lower value has been reported. The laboratory "P" flagged the affected samples due to the out of quality control parameter.

#### 3.0 INORGANIC DATA VALIDATION RESULTS

The Results of START's inorganic data validation are summarized below by QC audit review. After the START project staff received the data packages, they were inventoried for completeness and then reviewed according to matrix-specific protocols and data quality objectives established for the project.

### 3.1 TOTAL AND TCLP METALS BY METHOD 6010B AND TOTAL AND TCLP MERCURY BY 7470A.

#### 3.1.1 SAMPLE HANDLING

Chain of custody documentation and sample receipt forms were reviewed to ensure requested analyses were performed and that samples arrived at the laboratory intact. Soil samples were received with no discrepancies noted by the lab.

#### 3.1.2 SAMPLE PRESERVATION AND HOLDING TIME

Samples were analyzed within the holding time criteria. No discrepancies were noted.

#### 3.1.3 BLANK RESULTS

The purpose of laboratory (or field) blank analysis is to determine the existence and magnitude of contamination resulting from laboratory (or field) activities. Laboratory method blank samples for TCLP mercury analyses, LB-500-116867/1-B, LB2-500-116869/1-B, MB-500-116975/7-A were run with batch number 116975. A laboratory method blank sample for TCLP metals LB2-500-116869/1-C was run with batch number 116990. A laboratory method blank sample for Total mercury, MB-500-116821/7-A was run with batch number 116821.

The following method blank samples deficiencies were noted: The laboratory method blank sample for Total metals analyses, MB-500-116743/1-A detected chromium at 0.223 mg/Kg above the MDL of 0.085 mg/Kg and below the RL of 1.0 mg/Kg. The laboratory "J" flagged the estimated quantitation. The laboratory method blank for TCLP metal analyses, LB-500-116867/1-C detected copper at 0.0141 mg/L above the MDL of 0.010 mg/L and below the RL of 0.025 mg/L. The laboratory "J" flagged the estimated quantitation. All affected samples (500-35461-2, 500-35461-3, 500-35461-4 and 500-35461-12) were "B" flagged due to the compounds found in the method blank samples.

Data Validation for Rockford Package Page 8

#### 3.1.4 LCS/LCSD RECOVERY RESULTS

Data for the LCS/LCSD is generated to provide information on the accuracy of the analytical method and on the laboratory performance. The LCS is fortified with the full list of metals and analyzed with each batch of samples. The LCS accuracy performance is measured by Percent Recovery (%R). A LCS for TCLP metals (LCS-500-116743/2-A) was analyzed for batch number 116743. A LCS for TCLP mercury (LCS-500-116975/8-A) was analyzed for batch number 116975. A LCS for Total metals (LCS-500-116990/3A) was analyzed for batch number 116990. A LCS for Total mercury (LCS-500-116821/8-A) was analyzed for batch number 116821.

No other discrepancies were noted.

#### 3.1.5 DULPICATE RESULTS

Duplicate analyses were not performed on laboratory SDG number 500-35461-1 due to the nature of the waste sample stream.

No deficiencies were noted.

## 3.2 GENERAL CHEMISTRY. FLASHPOINT BY METHOD 1010, pH by method 9040B AND ASBESTOS PLM BY EPA-600/M4-82-020 & EPA METHOD 600/R-93-116

#### 3.2.1 SAMPLE HANDLING

Chain of custody documentation and sample receipt forms were reviewed to ensure requested analyses were performed and that samples arrived at the laboratory intact. Soil samples were received with no discrepancies noted by the lab.

#### 3.2.2 SAMPLE PRESERVATION AND HOLDING TIME

Samples were analyzed within the holding time criteria. No discrepancies were noted.

#### 3.2.3 BLANK RESULTS

Due to the methodologies, method blanks were not associated with the general chemistry package.

#### 3.2.4 DULPICATE RESULTS

Duplicate analyses were performed on laboratory SDG number 500-35461-1 due to the nature of the waste sample stream. Data for the duplicate samples were generated to provide information on the accuracy of the analytical method and on the laboratory performance. The duplicate sample accuracy performance is measured by Relative Percent Difference (%RPD).

The following duplicate samples were associated with the general chemistry analyses for pH: 500-35461-5, 500-35461-6, 500-35461-7, 500-35461-8, 500-35461-9, 500-35461-10 and 500-35461-11.

Data Validation for Rockford Package Page 9

The following duplicate samples were associated with the general chemistry analyses for flashpoint: 500-35461-9 and 500-35461-11.

The %RPDs were all under quality control limits. No deficiencies were noted.

#### 3.2.5 ASBESTOS PLM

This method was subcontracted to P&K Microbiology. The subcontract certification is different from those listed on the TestAmerica cover page of this final report.

No deficiencies were noted.

#### 4.0 OVERALL ASSESSMENT OF DATA

The analytical results meet the data quality objectives defined by the applicable method and validation guidance documentation. The analytical data is usable and acceptable as reported by the laboratory.

A copy of the data reporting qualifiers for GC/MS VOA, GC/MS Semi VOA, GC Semi VOA, metals, and general chemistry is provided along with the signed Form Is (Forms IA and IB).

# ATTACHMENTS DATA REPORTING QUALIFIERS SUMMARY OF ANALYTICAL RESULTS CHAIN-OF-CUSTODY

# ATTACHMENT DATA REPORTING QUALIFIERS

#### DATA REPORTING QUALIFIERS

Client: Oneida Total Integrated Enterprises LLC

Description Lab Section Qualifier GC/MS VOA Indicates the analyte was analyzed for but not detected. LCS or LCSD exceeds the control limits Result is less than the RL but greater than or equal to the MDL and the concentration is an approximate value. Surrogate is outside control limits GC/MS Semi VOA ICV,CCV,ICB,CCB, ISA, ISB, CRI, CRA, DLCK or MRL standard: Instrument related QC exceeds the control limits. U Indicates the analyte was analyzed for but not detected. Result is less than the RL but greater than or equal to the MDL and the concentration is an approximate value. RPD of the LCS and LCSD exceeds the control limits Surrogate is outside control limits Surrogate or matrix spike recoveries were not obtained because the extract was diluted for analysis; also compounds analyzed at a dilution may be flagged with a D. GC Semi VOA U Indicates the analyte was analyzed for but not detected. J Result is less than the RL but greater than or equal to the MDL and the concentration is an approximate value. Surrogate is outside control limits The %RPD between the primary and confirmation column/detector is >40%. The lower value has been reported.

Job Number: 500-35461-1

#### **DATA REPORTING QUALIFIERS**

Client: Oneida Total Integrated Enterprises LLC

Lab Section	Qualifier	Description
Metals		
	В	Compound was found in the blank and sample.
	, 9	ICV,CCV,ICB,CCB, ISA, ISB, CRI, CRA, DLCK or MRL standard: Instrument related QC exceeds the control limits.
	U	Indicates the analyte was analyzed for but not detected.
	J	Result is less than the RL but greater than or equal to the MDL and the concentration is an approximate value.
General Chemistry		
	HF	Field parameter with a holding time of 15 minutes
	U	Indicates the analyte was analyzed for but not detected.

Job Number: 500-35461-1

# ATTACHMENT SUMMARY OF ANALYTICAL RESULTS

## Method 8260B

Volatile Organic Compounds (GC/MS) by Method 8260B

Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG No.:

Client Sample ID: RP-SOLID-01 Lab Sample ID: 500-35461-2

Matrix: Solid Lab File ID: 35461-02A.D

Analysis Method: 8260B Date Collected: 06/13/2011 12:10

Sample wt/vol: 5(g) Date Analyzed: 06/21/2011 23:38

Soil Aliquot Vol: 5 (mL) Dilution Factor: 50

Soil Extract Vol.: 5(mL) GC Column: DB624 ID: 0.2(mm)

% Moisture: 7.5 Level: (low/med) Medium

Analysis Batch No.: 117160 Units: mg/Kg

CAS NO.	COMPOUND NAME	RESULT	Q	RL	MDL
75-71-8	Dichlorodifluoromethane	0,11	0.0	0.11	0.039
74-87-3	Chloromethane	0.11	U	0.11	0.024
75-01-4	Vinyl chloride	0.014	U	0.014	0.0044
74-83-9	Bromomethane	0.11	U	0.11	0.036
75-00-3	Chloroethane	0.11	U.	0.11	0.032
75-69-4	Trichlorofluoromethane	0.11	U	0.11	0.020
75-35-4	1,1-Dichloroethene	0.054	U	0.054	0.016
75-15-0	Carbon disulfide	0.27	U	0.27	0.021
67-64-1	Acetone	0.27	U	0.27	0.13
75-09-2	Methylene Chloride	0.38		0.27	0.032
156-60-5	trans-1,2-Dichloroethene	0.16		0.054	0.019
1634-04-4	Methyl tert-butyl ether	0.11	U	0.11	0.016
75-34-3	1,1-Dichloroethane	0.054	U	0.054	0.010
594-20-7	2,2-Dichloropropane	0.054	U	0.054	0.013
156-59-2	cis-1,2-Dichloroethene	0.054	U	0.054	0.016
78-93-3	2-Butanone (MEK)	0.27	U	0.27	0.10
74-97-5	Bromochloromethane	0.11	U	0.11	0.045
67-66-3	Chloroform	0.054	D	0.054	0.0079
71-55-6	1,1,1-Trichloroethane	0.054	U	0.054	0.016
563-58-6	1,1-Dichloropropene	0.054	U	0.054	0.01
56-23-5	Carbon tetrachloride	0.054	U	0.054	0.024
71-43-2	Benzene	0.014	0	0.014	0.0060
107-06-2	1,2-Dichloroethane	0.054	U	0.054	0.013
79-01-6	Trichloroethene	0.025		0.014	0.0053
78-87-5	1,2-Dichloropropane	0.054	U	0.054	0.017
74-95-3	Dibromomethane	0.11	U	0.11	0.043
75-27-4	Bromodichloromethane	0.11	U	0.11	0.021
10061-01-5	cis-1,3-Dichloropropene	0.054	U	0.054	0.0089
108-10-1	4-Methyl-2-pentanone (MIBK)	0.27	U	0.27	0.059
108-88-3	Toluene	0.034		0.014	0.0043
10061-02-6	trans-1,3-Dichloropropene	0.054	U	0.054	0.015
79-00-5	1,1,2-Trichloroethane	0.054	υ	0.054	0.024
127-18-4	Tetrachloroethene	0.054	υ	0.054	0.015
142-28-9	1,3-Dichloropropane	0.054	U	0.054	0.015
591-78-6	2-Hexanone	0.27	Ü	0.27	0.051
124-48-1	Dibromochloromethane	0,11	U	0.11	0.022

7/19/W

Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG No.:

Client Sample ID: RP-SOLID-01 Lab Sample ID: 500-35461-2

Matrix: Solid Lab File ID: 35461-02A.D

Analysis Method: 8260B Date Collected: 06/13/2011 12:10

Sample wt/vol: 5(g) Date Analyzed: 06/21/2011 23:38

Soil Aliquot Vol: 5 (mL) Dilution Factor: 50

Soil Extract Vol.: 5(mL) GC Column: DB624 ID: 0.2(mm)

% Moisture: 7.5 Level: (low/med) Medium

CAS NO.	COMPOUND NAME	RESULT	Q	RL	MDL
106-93-4	1,2-Dibromoethane	0.11	U	0.11	0.037
108-90-7	Chlorobenzene	0.054	U	0.054	0.012
630-20-6	1,1,1,2-Tetrachloroethane	0.11	Ü	0.11	0.012
100-41-4	Ethylbenzene	0.0094	3	0.014	0.0053
179601-23-1	m&p-Xylene	0.055		0.027	0.012
95-47-6	o-Xylene	0.043		0.014	0.0027
100-42-5	Styrene	0.054	Ü	0.054	0.017
75-25-2	Bromoform	0.11	U	0.11	0.028
98-82-8	Isopropylbenzene	0.11	U	0.11	0.018
108-86-1	Bromobenzene	0.11	υ	0.11	0.017
79-34-5	1,1,2,2-Tetrachloroethane	0.054	U	0.054	0.017
96-18-4	1,2,3-Trichloropropane	0,11	U	0.11	0.036
103-65-1	N-Propylbenzene	0.11	U	0.11	0.011
95-49-8	2-Chlorotoluene	0.054	U	0.054	0.012
108-67-8	1,3,5-Trimethylbenzene	0.11	U	0.11	0.016
106-43-4	4-Chlorotoluene	0.054	D	0.054	0.010
98-06-6	tert-Butylbenzene	0.054	U	0.054	0.013
95-63-6	1,2,4-Trimethylbenzene	0.040	3	0.11	0.014
135-98-8	sec-Butylbenzene	0.054	Ü	0.054	0.011
99-87-6	p-Isopropyltoluene	0.11	U	0.11	0.016
104-51-8	n-Butylbenzene	0.054	U	0.054	0.010
96-12-8	1,2-Dibromo-3-Chloropropane	0.11	0	0.11	0.032
87-61-6	1,2,3-Trichlorobenzene	0.11	n . 0	0.11	0.040

CAS NO.	SURROGATE	RREC	0	LIMITS
17060-07-0	1,2-Dichloroethane-d4 (Surr)	95		77-124
2037-26-5	Toluene-d8 (Surr)	105		80-121
460-00-4	4-Bromofluorobenzene (Surr)	92		77-112
1868-53-7	Dibromofluoromethane	100		78-119



Lab Name: TestAmerica Chicago Job No.: 500-35461-1			
SDG No.:			
Client Sample ID: RP-SOLID-01	Lab Sample ID: 500-35461-2		
Matrix: Solid (TCLP)	Lab File ID: 35461-02.D		
Analysis Method: 8260B	Date Collected: 06/13/2011 12:10		
Sample wt/vol: 5(mL)	Date Analyzed: 06/21/2011 21:16		
Soil Aliquot Vol:	Dilution Factor: 20		
Soil Extract Vol.:	GC Column: DB624 ID: 0.2(mm)		
% Moisture:	Level: (low/med) Low		
Analysis Batch No.: 117161	Units: mg/L		

CAS NO.	COMPOUND NAME	RESULT	Q	RL	MDL
71-43-2	Benzene	0.020	U	0.020	0.010
56-23-5	Carbon tetrachloride	0.020	υ	0.020	0.010
108-90-7	Chlorobenzene	0.020	U	0.020	0.010
67-66-3	Chloroform	0.020	U	0.020	0.010
107-06-2	1,2-Dichloroethane	0.020	U	0.020	0.010
75-35-4	1,1-Dichloroethene	0,020	U	0.020	0.010
78-93-3	2-Butanone (MEK)	0.10	0	0.10	0.050
127-18-4	Tetrachloroethene	0.020	U	0.020	0.010
79-01-6	Trichloroethene	0.020	U	0.020	0.010
75-01-4	Vinyl chloride	0.020	U	0.020	0.010

CAS NO.	SURROGATE	%REC	Q	LIMITS
17060-07-0	1,2-Dichloroethane-d4 (Surr)	87		77-124
2037-26-5	Toluene-d8 (Surr)	97		80-121
460-00-4	4-Bromofluorobenzene (Surr)	87		77-112
1868-53-7	Dibromofluoromethane	95		78-119

Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG No.:

Client Sample ID: RF-SOLID-02 Lab Sample ID: 500-35461-3

Matrix: Solid Lab File ID: 35461-03A.D

Analysis Method: 8260B Date Collected: 06/13/2011 12:20

Sample wt/vol: 5(g) Date Analyzed: 06/22/2011 00:02

Soil Aliquot Vol: 5 (mL) Dilution Factor: 50

Soil Extract Vol.: 5(mL) GC Column: DB624 ID: 0.2(mm)

% Moisture: 34.4 Level: (low/med) Medium

CAS NO.	COMPOUND NAME	RESULT	0	RL	MDL
75-71-8	Dichlorodifluoromethane	0.15	n . O	0.15	0.055
74-87-3	Chloromethane	0.15	U	0.15	0.033
75-01-4	Vinyl chloride	0.019	U	0.019	0.0062
74-83-9	Bromomethane	0.15	υ	0.15	0.051
75-00-3	Chloroethane	0.15	U	0.15	0.045
75-69-4	Trichlorofluoromethane	0.15	U	0.15	0.028
75-35-4	1,1-Dichloroethene	0.076	U	0.076	0.023
75-15-0	Carbon disulfide	0.38	U	0.38	0.030
67-64-1	Acetone	0.38	U	0.38	0.18
75-09-2	Methylene Chloride	0.38	U	0.38	0.046
156-60-5	trans-1,2-Dichloroethene	0.076	U	0.076	0.026
1634-04-4	Methyl tert-butyl ether	0.15	Ü	0.15	0.023
75-34-3	1,1-Dichloroethane	0.076	U	0.076	0.015
594-20-7	2,2-Dichloropropane	0.076	U	0.076	0.019
156-59-2	cis-1,2-Dichloroethene	0.076	U	0.076	0.023
78-93-3	2-Butanone (MEK)	0.38	U	0.38	0.14
74-97-5	Bromochloromethane	0.15	U	0.15	0.063
67-66-3	Chloroform	0.076	U	0.076	0.011
71-55-6	1,1,1-Trichloroethane	0.076	U	0.076	0.022
563-58-6	1,1-Dichloropropene	0.076	U	0.076	0.022
56-23-5	Carbon tetrachloride	0.076	U	0.076	0.034
71-43-2	Benzene	0.019	U	0.019	0.0085
107-06-2	1,2-Dichloroethane	0.076	U	0.076	0.018
79-01-6	Trichloroethene	0.019	U	0.019	0.0075
78-87-5	1,2-Dichloropropane	0.076	U	0.076	0.023
74-95-3	Dibromomethane	0.15	U	0.15	0.060
75-27-4	Bromodichloromethane	0.15	U	0.15	0.030
10061-01-5	cis-1,3-Dichloropropene	0.076	U	0.076	0.012
108-10-1	4-Methyl-2-pentanone (MIBK)	0.38	U	0.38	0.084
108-88-3	Toluene	0.019	U	0.019	0.0061
10061-02-6	trans-1,3-Dichloropropene	0.076	U	0.076	0.027
79-00-5	1,1,2-Trichloroethane	0.076	U	0.076	0.033
127-18-4	Tetrachloroethene	0.076	U	0.076	0.021
142-28-9	1,3-Dichloropropane	0.076	ti	0.076	0.021
591-78-6	2-Hexanone	0.38	U	0.38	0.071
124-48-1	Dibromochloromethane	0.15	U	0.15	0.031



Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG No.:

Client Sample ID: RP-SOLID-02 Lab Sample ID: 500-35461-3

Matrix: Solid Lab File ID: 35461-03A.D

Analysis Method: 8260B Date Collected: 06/13/2011 12:20

Sample wt/vol: 5(g) Date Analyzed: 06/22/2011 00:02

Soil Aliquot Vol: 5 (mL) Dilution Factor: 50

Soil Extract Vol.: 5(mL) GC Column: DB624 ID: 0.2(mm)

\* Moisture: 34.4 Level: (low/med) Medium

CAS NO.	COMPOUND NAME	RESULT	Q	RL	MDL
106-93-4	1,2-Dibromoethane	0.15	D	0.15	0.052
108-90-7	Chlorobenzene	0.076	U	0.076	0.017
630-20-6	1,1,1,2-Tetrachloroethane	0.15	U	0.15	0.017
100-41-4	Ethylbenzene	0.019	U	0.019	0.0075
179601-23-1	m&p-Xylene	0.038	ū	0.038	0.017
95-47-6	o-Xylene	0.014	J	0.019	0.0038
100-42-5	Styrene	0.076	U	0.076	0.024
75-25-2	Bromoform	0.15	Ü	0.15	0.039
98-82-8	Isopropylbenzene	0.15	U	0.15	0.026
108-86-1	Bromobenzene	0.15	U	0.15	0.024
79-34-5	1,1,2,2-Tetrachloroethane	0.076	U	0.076	0.024
96-18-4	1,2,3-Trichloropropane	0.15	U	0.15	0.051
103-65-1	N-Propylbenzene	0.15	υ	0.15	0.016
95-49-8	2-Chlorotoluene	0.076	U	0.076	0.017
108-67-8	1,3,5-Trimethylbenzene	0.15	U	0.15	0.023
106-43-4	4-Chlorotoluene	0.076	U	0.076	0.015
98-06-6	tert-Butylbenzene	0.076	U	0.076	0.018
95-63-6	1,2,4-Trimethylbenzene	0.15	U:	0.15	0.019
135-98-8	sec-Butylbenzene	0.076	υ	0.076	0.015
99-87-6	p-Isopropyltoluene	0.15	U	0.15	0.023
104-51-8	n-Butylbenzene	0.076	U	0.076	0.014
96-12-8	1,2-Dibromo-3-Chloropropane	0.15	U	0.15	0.045
87-61-6	1,2,3-Trichlorobenzene	0.15	0 . 0	0.15	0.056

CAS NO.	SURROGATE	%REC	Q	LIMITS
17060-07-0	1,2-Dichloroethane-d4 (Surr)	101		77-124
2037-26-5	Toluene-d8 (Surr)	110		80-121
460-00-4	4-Bromofluorobenzene (Surr)	99		77-112
1868-53-7	Dibromofluoromethane	104		78-119

Lab Name: TestAmerica Chicago	Job No.: 500-35461-1
SDG No.:	
Client Sample ID: RP-SOLID-02	Lab Sample ID: 500-35461-3
Matrix: Solid (TCLP)	Lab File ID: 35461-03.D
Analysis Method: 8260B	Date Collected: 06/13/2011 12:20
Sample wt/vol: 5(mL)	Date Analyzed: 06/21/2011 21:40
Soil Aliquot Vol:	Dilution Factor: 20
Soil Extract Vol.:	GC Column: DB624 ID: 0.2(mm)
% Moisture:	Level: (low/med) Low
Analysis Batch No.: 117161	Units: mg/L

CAS NO.	COMPOUND NAME	RESULT	0	RL	MDL
71-43-2	Benzene	0.020	U	0.020	0.010
56-23-5	Carbon tetrachloride	0.020	U	0.020	0.010
108-90-7	Chlorobenzene	0.020	U	0.020	0.010
67-66-3	Chloroform	0.020	U	0.020	0.010
107-06-2	1,2-Dichloroethane	0.020	U	0.020	0.010
75-35-4	1,1-Dichloroethene	0.020	U	0.020	0.010
78-93-3	2-Butanone (MEK)	0.10	U	0.10	0.050
127-18-4	Tetrachloroethene	0.020	U	0.020	0.010
79-01-6	Trichloroethene	0.020	ū	0.020	0.010
75-01-4	Vinyl chloride	0.020	U	0.020	0.010

CAS NO.	SURROGATE	*REC	Q	LIMITS
17060-07-0	1,2-Dichloroethane-d4 (Surr)	91		77-124
2037-26-5	Toluene-d8 (Surr)	101		80-121
460-00-4	4-Bromofluorobenzene (Surr)	90		77-112
1868-53-7	Dibromofluoromethane	100		78-119



Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG No.:

Client Sample ID: RP-SOLID-03 Lab Sample ID: 500-35461-4

Matrix: Solid Lab File ID: 35461-04A.D

Analysis Method: 8260B Date Collected: 06/13/2011 12:30

Sample wt/vol: 5(g) Date Analyzed: 06/22/2011 00:25

Soil Aliquot Vol: 5 (mL) Dilution Factor: 50

Soil Extract Vol.: 5(mL) GC Column: DB624 ID: 0.2(mm)

Moisture: 6.2 Level: (low/med) Medium

Analysis Batch No.: 117160 Units: mg/Kg

CAS NO.	COMPOUND NAME	RESULT	0	RL	MDL
75-71-8	Dichlorodifluoromethane	0.11	U • O	0.11	0.039
74-87-3	Chloromethane	0.11	U	0.11	0.023
75-01-4	Vinyl chloride	0.013	U	0.013	0.0044
74-83-9	Bromomethane	0.11	U	0.11	0.035
75-00-3	Chloroethane	0.11	U	0.11	0.031
75-69-4	Trichlorofluoromethane	0.11	U	0.11	0.020
75-35-4	1,1-Dichloroethene	0.053	U	0.053	0.016
75-15-0	Carbon disulfide	0.27	U	0.27	0.021
67-64-1	Acetone	0.27	U	0.27	0.13
75-09-2	Methylene Chloride	0,27	U	0.27	0.032
156-60-5	trans-1,2-Dichloroethene	0.073		0.053	0.018
1634-04-4	Methyl tert-butyl ether	0.11	U	0.11	0.016
75-34-3	1,1-Dichloroethane	0.053	U	0.053	0.010
594-20-7	2,2-Dichloropropane	0.053	U	0.053	0.013
156-59-2	cis-1,2-Dichloroethene	0.053	U	0.053	0.016
78-93-3	2-Butanone (MEK)	0.27	U	0.27	0.10
74-97-5	Bromochioromethane	0.11	U	0.11	0.044
67-66-3	Chloroform	0.053	ū	0.053	0.0078
71-55-6	1,1,1-Trichloroethane	0.053	D	0.053	0.016
563-58-6	1,1-Dichloropropene	0.053	U	0.053	0.015
56-23-5	Carbon tetrachloride	0.053	υ	0.053	0.024
71-43-2	Benzene	0.013	U	0.013	0.0059
107-06-2	1,2-Dichloroethane	0.053	U	0.053	0.012
79-01-6	Trichloroethene	0.013	U	0.013	0.0053
78-87-5	1,2-Dichloropropane	0.053	υ	0.053	0.016
74-95-3	Dibromomethane	0.11	U	0.11	0.042
75-27-4	Bromodichloromethane	0.11	U	0.11	0.021
10061-01-5	cis-1,3-Dichloropropene	0.053	U	0.053	0.0087
108-10-1	4-Methyl-2-pentanone (MIBK)	0.27	U	0.27	0.059
108-88-3	Toluene	0.013	U	0.013	0.0043
10061-02-6	trans-1,3-Dichloropropene	0.053	U	0.053	0.019
79-00-5	1,1,2-Trichloroethane	0.053	U	0.053	0.023
127-18-4	Tetrachloroethene	0.053	U	0.053	0.015
142-28-9	1,3-Dichloropropane	0.053	U	0.053	0.015
591-78-6	2-Hexanone	0.27	U	0.27	0.050
124-48-1	Dibromochloromethane	0.11	Ü	0.11	0.022

7 19 11 06/23/2011

Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG No.:

Client Sample ID: RP-SOLID-03 Lab Sample ID: 500-35461-4

Matrix: Solid Lab File ID: 35461-04A.D

Analysis Method: 8260B Date Collected: 06/13/2011 12:30

Sample wt/vol: 5(g) Date Analyzed: 06/22/2011 00:25

Soil Aliquot Vol: 5 (mL) Dilution Factor: 50

Soil Extract Vol.: 5(mL) GC Column: DB624 ID: 0.2(mm)

% Moisture: 6.2 Level: (low/med) Medium

Analysis Batch No.: 117160 Units: mg/Kg

CAS NO.	COMPOUND NAME	RESULT	Q	RL	MDL
106-93-4	1,2-Dibromoethane	0.11	U	0.11	0.036
108-90-7	Chlorobenzene	0.053	U	0.053	0.012
630-20-6	1,1,1,2-Tetrachloroethane	0.11	U	0.11	0.012
100-41-4	Ethylbenzene	0.013	U	0.013	0.0052
179601-23-1	m&p-Xylene	0.027	U	0.027	0.012
95-47-6	o-Xylene	0.013	U	0.013	0.0027
100-42-5	Styrene	0.053	U	0.053	0.017
75-25-2	Bromoform	0.11	U	0.11	0.027
98-82-8	Isopropylbenzene	0.11	U	0.11	0.018
108-86-1	Bromobenzene	0.11	υ	0.11	0.017
79-34-5	1,1,2,2-Tetrachloroethane	0.053	υ	0.053	0.017
96-18-4	1,2,3-Trichloropropane	0.11	U	0.11	0.036
103-65-1	N-Propylbenzene	0.11	U	0.11	0.011
95-49-8	2-Chlorotoluene	0.053	U	0.053	0.012
108-67-8	1,3,5-Trimethylbenzene	0.11	U	0.11	0.016
106-43-4	4-Chlorotoluene	0.053	U	0.053	0.010
98-06-6	tert-Butylbenzene	0.053	U	0.053	0.013
95-63-6	1,2,4-Trimethylbenzene	0.11	υ	0.11	0.013
135-98-8	sec-Butylbenzene	0.053	υ	0.053	0.011
99-87-6	p-Isopropyltoluene	0.11	U	0.11	0.016
104-51-8	n-Butylbenzene	0.053	U	0.053	0.010
96-12-8	1,2-Dibromo-3-Chloropropane	0.11	U	0.11	0.031
87-61-6	1,2,3-Trichlorobenzene	0.11	U * ()	0.11	0.039

CAS NO.	SURROGATE	*REC	0	LIMITS
17060-07-0	1,2-Dichloroethane-d4 (Surr)	95		77-124
2037-26-5	Toluene-d8 (Surr)	103		80-121
460-00-4	4-Bromofluorobenzene (Surr)	95		77-112
1868-53-7	Dibromofluoromethane	99		78-119

Jus 119/11

Lab Name: TestAmerica Chicago	Job No.: 500-35461-1
SDG No.:	
Client Sample ID: RP-SOLID-03	Lab Sample ID: 500-35461-4
Matrix: Solid (TCLP)	Lab File ID: 35461-04.D
Analysis Method: 8260B	Date Collected: 06/13/2011 12:30
Sample wt/vol: 5(mL)	Date Analyzed: 06/21/2011 22:03
Soil Aliquot Vol:	Dilution Pactor: 20
Soil Extract Vol.:	GC Column: DB624 ID: 0.2(mm)
% Moisture:	Level: (low/med) Low
Analysis Batch No.: 117161	Units: mg/L

CAS NO.	COMPOUND NAME	RESULT	0	RL	MDL
71-43-2	Benzene	0.020	U	0.020	0.010
56-23-5	Carbon tetrachloride	0.020	U	0.020	0.010
108-90-7	Chlorobenzene	0.020	U	0.020	0.010
67-66-3	Chloroform	0.020	U	0.020	0.010
107-06-2	1,2-Dichloroethane	0.020	U	0.020	0.010
75-35-4	1,1-Dichloroethene	0.020	U	0.020	0.010
78-93-3	2-Butanone (MEK)	0.10	Ü	0.10	0.050
127-18-4	Tetrachloroethene	0.020	U	0.020	0.010
79-01-6	Trichloroethene	0.020	U	0.020	0.010
75-01-4	Vinyl chloride	0.020	U	0.020	0.010

CAS NO.	SURROGATE	*REC	Q	LIMITS
17060-07-0	1,2-Dichloroethane-d4 (Surr)	95		77-124
2037-26-5	Toluene-d8 (Surr)	106		80-121
460-00-4	4-Bromofluorobenzene (Surr)	94		77-112
1868-53-7	Dibromofluoromethane	106		78-119

Job No.: 500-35461-1			
Lab Sample ID: 500-35461-9			
Lab File ID: 35461-09B.D			
Date Collected: 06/13/2011 14:00			
Date Analyzed: 06/22/2011 01:36			
Dilution Factor: 10			
GC Column: DB624 ID: 0.2(mm)			
Level: (low/med) Low			
Units: mg/L			

CAS NO.	COMPOUND NAME	RESULT	0	RL	MDL
75-71-8	Dichlorodifluoromethane	0.010	·ti	0.010	0.0026
74-87-3	Chloromethane	0.010	U	0.010	0.0024
75-01-4	Vinyl chloride	0.0050	U	0.0050	0.0013
74-83-9	Bromomethane	0.010	U	0.010	0.0049
75-00-3	Chloroethane	0.010	U	0.010	0.0033
75-69-4	Trichlorofluoromethane	0.010	U	0.010	0.0022
75-35-4	1,1-Dichloroethene	0.010	υ	0.010	0.0029
75-15-0	Carbon disulfide	0.050	U	0.050	0.0044
67-64-1	Acetone	0.14		0.050	0.019
75-09-2	Methylene Chloride	0.050	U	0.050	0.0063
156-60-5	trans-1,2-Dichloroethene	0.010	U	0.010	0.0027
1634-04-4	Methyl tert-butyl ether	0.010	υ	0.010	0.0028
75-34-3	1,1-Dichloroethane	0.010	U	0.010	0.0024
594-20-7	2,2-Dichloropropane	0.010	U	0.010	0.0031
156-59-2	cis-1,2-Dichloroethene	0.010	U	0.010	0.0022
78-93-3	2-Butanone (MEK)	0.050	U	0.050	0.010
74-97-5	Bromochloromethane	0.010	U	0.010	0.0050
67-66-3	Chloroform	0.010	Ü	0.010	0.0025
71-55-6	1,1,1-Trichloroethane	0.010	U	0.010	0.0026
563-58-6	1,1-Dichloropropene	0.010	ti	0.010	0.0025
56-23-5	Carbon tetrachloride	0.010	U	0.010	0.0028
71-43-2	Benzene	0.0050	Ü	0.0050	0.0012
107-06-2	1,2-Dichloroethane	0.010	n	0.010	0.0028
79-01-6	Trichloroethene	0,0050	U	0.0050	0.0018
78-87-5	1,2-Dichloropropane	0.010	U	0.010	0.0036
74-95-3	Dibromomethane	0.010	D	0.010	0.0039
75-27-4	Bromodichloromethane	0.010	υ	0.010	0.0023
10061-01-5	cis-1,3-Dichloropropene	0.010	U	0.010	0.0028
108-10-1	4-Methyl-2-pentanone (MIBK)	0.050	υ	0.050	0.0079
108-88-3	Toluene	0.0050	U	0.0050	0.0015
10061-02-6	trans-1,3-Dichloropropene	0,010	U	0,010	0.0035
79-00-5	1,1,2-Trichloroethane	0.010	U	0.010	0.0030
127-18-4	Tetrachloroethene	0.010	U	0.010	0.0022
142-28-9	1,3-Dichloropropane	0.010	U	0,010	0.0027
591-78-6	2-Hexanone	0.050	U	0.050	0.0056
124-48-1	Dibromochloromethane	0.010	n	0,010	0.0025

19/11 06/23

Lab Name: TestAmerica Chicago	Job No.: 500-35461-1
SDG No.:	
Client Sample ID: RP-DRUM-05	Lab Sample ID: 500-35461-9
Matrix: Water	Lab File ID: 35461-09B.D
Analysis Method: 8260B	Date Collected: 06/13/2011 14:00
Sample wt/vol: 5(mL)	Date Analyzed: 06/22/2011 01:36
Soil Aliquot Vol:	Dilution Factor: 10
Soil Extract Vol.:	GC Column: DB624 ID: 0.2(mm)
% Moisture:	Level: (low/med) Low
Analysis Batch No.: 117161	Units: mg/L

CAS NO.	COMPOUND NAME	RESULT	0	RL.	MDL
106-93-4	1,2-Dibromoethane	0.010	U	0.010	0.0045
108-90-7	Chlorobenzene	0.010	U	0.010	0.0024
630-20-6	1,1,1,2-Tetrachloroethane	0.010	U	0.010	0.0031
100-41-4	Ethylbenzene	0.030		0.0050	0.0014
179601-23-1	m&p-Xylene	0.010	U	0.010	0.0030
95-47-6	o-Xylene	0.10		0.0050	0.0013
100-42-5	Styrene	0.010	U	0.010	0.0026
75-25-2	Bromoform	0.010	U	0.010	0.0045
98-82-8	Isopropylbenzene	0.010	Ü	0.010	0.0021
108-86-1	Bromobenzene	0.010	U	0.010	0.0031
79-34-5	1,1,2,2-Tetrachloroethane	0.010	Ü	0.010	0.0035
96-18-4	1,2,3-Trichloropropane	0.010	U	0.010	0.0060
103-65-1	N-Propylbenzene	0.0059	J	0.010	0.0019
95-49-8	2-Chlorotoluene	0.010	U	0.010	0.0021
108-67-8	1,3,5-Trimethylbenzene	0.015		0.010	0.0023
106-43-4	4-Chlorotoluene	0.010	U	0.010	0.0021
98-06-6	tert-Butylbenzene	0.010	U	0.010	0.0024
95-63-6	1,2,4-Trimethylbenzene	0.047		0.010	0.0022
135-98-8	sec-Butylbenzene	0.010	U	0.010	0.0019
99-87-6	p-Isopropyltoluene	0.010	U.	0.010	0.0024
104-51-8	n-Butylbenzene	0.010	ti ti	0.010	0.0021
96-12-8	1,2-Dibromo-3-Chloropropane	0.020	U	0.020	0.012
87-61-6	1,2,3-Trichlorobenzene	0.011		0.010	0.0036

CAS NO.	SURROGATE	*REC	Q	LIMITS
17060-07-0	1,2-Dichloroethane-d4 (Surr)	99		77-124
2037-26-5	Toluene-d8 (Surx)	103		80-121
460-00-4	4-Bromofluorobenzene (Surr)	118	X	77-112
1868-53-7	Dibromofluoromethane	5	X	78-119

Job No.: 500-35461-1 Lab Name: TestAmerica Chicago SDG No.: Client Sample ID: RP-DRUM-05 Lab Sample ID: 500-35461-9 Matrix: Water (TCLP) Lab File ID: 35461-09,D Analysis Method: 8260B Date Collected: 06/13/2011 14:00 Sample wt/vol: 5(mL) Date Analyzed: 06/17/2011 22:50 Soil Aliquot Vol: Dilution Factor: 20 Soil Extract Vol.: GC Column: DB624 ID: 0.2(mm) % Moisture; Level: (low/med) Low Analysis Batch No.: 116824 Units: mg/L

CAS NO.	COMPOUND NAME	RESULT	Q	RL	MDL
71-43-2	Benzene	0.020	U	0.020	0.010
56-23-5	Carbon tetrachloride	0.020	U	0.020	0.010
108-90-7	Chlorobenzene	0.020	U	0.020	0.010
67-66-3	Chloroform	0.020	U	0.020	0.010
107-06-2	1,2-Dichloroethane	0.020	U	0.020	0.010
75-35-4	1,1-Dichloroethene	0.020	ti	0.020	0.010
78-93-3	2-Butanone (MEK)	0.10	U	0.10	0.050
127-18-4	Tetrachloroethene	0.020	D.	0.020	0.010
79-01-6	Trichloroethene	0.020	Ü	0.020	0.010
75-01-4	Vinyl chloride	0.020	U	0.020	0.010

CAS NO.	SURROGATE	*REC	Q	LIMITS
17060-07-0	1,2-Dichloroethane-d4 (Surr)	103		77-124
2037-26-5	Toluene-d8 (Surr)	99		80-121
460-00-4	4-Bromofluorobenzene (Surr)	95		77-112
1868-53-7	Dibromofluoromethane	10	X	78-119

Lab Name: TestAmerica Chicago	Job No.: 500-35461-1
SDG No.:	
Client Sample ID: RP-DRUM-07	Lab Sample ID: 500-35461-11
Matrix: Water	Lab File ID: 35461-11B.D
Analysis Method: 8260B	Date Collected: 06/13/2011 14:30
Sample wt/vol: 5(mL)	Date Analyzed: 06/22/2011 02:24
Soil Aliquot Vol:	Dilution Factor: 100
Soil Extract Vol.:	GC Column: DB624 ID: 0.2(mm)
% Moisture:	Level: (low/med) Low
Analysis Batch No.: 117161	Units: mg/L

CAS NO.	COMPOUND NAME	RESULT	0	RL	MDL
75-71-8	Dichlorodifluoromethane	0.10	U	0.10	0.026
74-87-3	Chloromethane	0.10	U	0.10	0.024
75-01-4	Vinyl chloride	0.050	U	0.050	0.013
74-83-9	Bromomethane	0.10	U	0.10	0.049
75-00-3	Chloroethane	0.10	U	0.10	0.033
75-69-4	Trichlorofluoromethane	0,10	U	0.10	0.022
75-35-4	1,1-Dichloroethene	0.10	U	0.10	0.029
75-15-0	Carbon disulfide	0.50	U	0.50	0.044
75-09-2	Methylene Chloride	0.66		0.50	0.063
156-60-5	trans-1,2-Dichloroethene	0.10	U	0.10	0.027
1634-04-4	Methyl tert-butyl ether	0.17		0.10	0.028
75-34-3	1,1-Dichloroethane	0.10	U	0.10	0.024
594-20-7	2,2-Dichloropropane	0.10	U	0.10	0.031
156-59-2	cis-1,2-Dichloroethene	0.10	U	0.10	0.022
78-93-3	2-Butanone (MEK)	0.50	ti	0.50	0.10
74-97-5	Bromochloromethane	0.10	U	0.10	0.050
67-66-3	Chloroform	0.10	U	0.10	0.025
71-55-6	1,1,1-Trichloroethane	0.10	U	0.10	0.026
563-58-6	1,1-Dichloropropene	0.10	U	0.10	0.025
56-23-5	Carbon tetrachloride	0.10	U	0.10	0.028
71-43-2	Benzene	0.068		0.050	0.012
107-06-2	1,2-Dichloroethane	0.10	U	0.10	0.028
79-01-6	Trichloroethene	0.050	U	0.050	0.018
78-87-5	1,2-Dichloropropane	0.10	U	0.10	0.036
74-95-3	Dibromomethane	0.10	υ	0.10	0.039
75-27-4	Bromodichloromethane	0.10	U	0.10	0.023
10061-01-5	cis-1,3-Dichloropropene	0.10	Ü	0.10	0.028
108-10-1	4-Methyl-2-pentanone (MIBK)	0.50	U	0.50	0.079
108-88-3	Toluene	0.050	U	0.050	0.015
10061-02-6	trans-1,3-Dichloropropene	0.10	U	0.10	0.035
79-00-5	1,1,2-Trichloroethane	0.10	U	0.10	0.030
127-18-4	Tetrachloroethene	0.10	U	0.10	0.022
142-28-9	1,3-Dichloropropane	0.10	U	0.10	0.027
591-78-6	2-Hexanone	0.50	Ü	0.50	0.056
124-48-1	Dibromochloromethane	0.10	U	0.10	0.025
106-93-4	1,2-Dibromoethane	0.10	U	0.10	0.045



Lab Name: TestAmerica Chicago Job No.: 500-35461-1 SDG No.: Client Sample ID: RP-DRUM-07 Lab Sample ID: 500-35461-11 Matrix: Water Lab File ID: 35461-11B.D Analysis Method: 8260B Date Collected: 06/13/2011 14:30 Sample wt/vol: 5(mL) Date Analyzed: 06/22/2011 02:24 Soil Aliquot Vol: Dilution Factor: 100 Soil Extract Vol.: GC Column: DB624 ID: 0.2(mm) % Moisture: Level: (low/med) Low Analysis Batch No.: 117161 Units: mg/L

CAS NO.	COMPOUND NAME	RESULT	Q	RL	MDL
108-90-7	Chlorobenzene	0.10	U	0.10	0.024
630-20-6	1,1,1,2-Tetrachloroethane	0.10	U	0.10	0.031
100-41-4	Ethylbenzene	0.57		0.050	0.014
179601-23-1	m&p-Xylene	0.10	U	0.10	0.030
95-47-6	o-Xylene	0.050	U	0.050	0.013
100-42-5	Styrene	0.10	U	0.10	0.026
75-25-2	Bromoform	0.10	U	0.10	0.045
98-82-8	Isopropylbenzene	0.37		0.10	0.021
108-86-1	Bromobenzene	0.10	U	0.10	0.031
79-34-5	1,1,2,2-Tetrachloroethane	0.10	-0	0.10	0.035
96-18-4	1,2,3-Trichloropropane	0.10	U	0.10	0.060
103-65-1	N-Propylbenzene	0.10	U	0.10	0.019
95-49-8	2-Chlorotoluene	0.10	U	0.10	0.021
108-67-8	1,3,5-Trimethylbenzene	0.10	U	0.10	0.023
106-43-4	4-Chlorotoluene	0.10	U	0.10	0.021
98-06-6	tert-Butylbenzene	0.10	U	0.10	0.024
95-63-6	1,2,4-Trimethylbenzene	0.10	U	0.10	0.022
135-98-8	sec-Butylbenzene	0.10	U	0.10	0.019
99-87-6	p-Isopropyltoluene	0.10	U	0.10	0.024
104-51-8	n-Butylbenzene	0.10	U	0.10	0.021
96-12-8	1,2-Dibromo-3-Chloropropane	0.20	U	0.20	0.12
87-61-6	1,2,3-Trichlorobenzene	0.10	U	0.10	0.036

CAS NO.	SURROGATE	%REC	Q	LIMITS
17060-07-0	1,2-Dichloroethane-d4 (Surr)	96		77-124
2037-26-5	Toluene-d8 (Surr)	104		80-121
460-00-4	4-Bromofluorobenzene (Surr)	113	X	77-112
1868-53-7	Dibromofluoromethane	4	X	78-119

Lab Name: TestAm	erica Chicago	Job No.: 500-35461-1				
SDG No.:						
Client Sample ID:	RP-DRUM-07 DL	Lab Sample ID:	500+354	61-11 DL		
Matrix: Water		Lab File ID: 35461-11D.D				
Analysis Method:	8260B	Date Collected: 06/13/2011 14:30				
Sample wt/vol: 5(mL)		Date Analyzed: 06/22/2011 11:26				
Soil Aliquot Vol:		Dilution Factor	5000			
Soil Extract Vol.		GC Column: DB62	24	ID: 0	,2 (mm)	
% Moisture:		Level: (low/med	Low			
Analysis Batch No	.: 117281	Units: mg/L				
CAS NO.	COMPOUND NAME	RESULT	0	RL	MDL	

CAS NO.	SURROGATE	%REC	Q	LIMITS
17060-07-0	1,2-Dichloroethane-d4 (Surr)	91		77-124
2037-26-5	Toluene-d8 (Surr)	102		80-121
460-00-4	4-Bromofluorobenzene (Surr)	93		77-112
1868-53-7	Dibromofluoromethane	92		78-119

Acetone

Lab Name: TestAmerica Chicago	Job No.: 500-35461-1
SDG No.:	
Client Sample ID: RP-DRUM-07	Lab Sample ID: 500-35461-11
Matrix: Water (TCLP)	Lab File ID: 35461-11.D
Analysis Method: 8260B	Date Collected: 06/13/2011 14:30
Sample wt/vol: 5(mL)	Date Analyzed: 06/17/2011 22:26
Soil Aliquot Vol:	Dilution Factor: 100
Soil Extract Vol.:	GC Column: DB624 ID: 0.2(mm)
% Moisture:	Level: (low/med) Low
Analysis Batch No.: 116824	Units: mg/L

CAS NO.	COMPOUND NAME	RESULT	Q	RL	MDL
71-43-2	Benzene	0.10	U	0.10	0.050
56-23-5	Carbon tetrachloride	0.10	U	0.10	0.050
108-90-7	Chlorobenzene	0.10	υ	0.10	0.050
67-66-3	Chloroform	0.10	U	0.10	0.050
107-06-2	1,2-Dichloroethane	0.10	U	0.10	0.050
75-35-4	1,1-Dichloroethene	0.10	U	0.10	0.050
78-93-3	2-Butanone (MEK)	0.50	U	0.50	0.25
127-18-4	Tetrachloroethene	0.10	U	0.10	0.050
79-01-6	Trichloroethene	0.10	D	0.10	0.050
75-01-4	Vinyl chloride	0.10	U	0.10	0.050

CAS NO.	SURROGATE	%REC	Q	LIMITS
17060-07-0	1,2-Dichloroethane-d4 (Surr)	101		77-124
2037-26-5	Toluene-d8 (Surr)	101		80-121
460-00-4	4-Bromofluorobenzene (Surr)	99		77-112
1868-53-7	Dibromofluoromethane	7	X	78-119

Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG No.:

Client Sample ID: RP-SOLID-04 Lab Sample ID: 500-35461-12

Matrix: Solid Lab File ID: 5461-13B.D

Analysis Method: 8260B Date Collected: 06/13/2011 12:45

Sample wt/vol: 5(g) Date Analyzed: 06/22/2011 13:23

Soil Aliquot Vol: Dilution Factor: 10

Soil Extract Vol.: GC Column: DB624 ID: 0.2(mm)

% Moisture: 9.6 Level: (low/med) Low

Analysis Batch No.: 117181 Units: mg/Kg

CAS NO.	COMPOUND NAME	RESULT	Q	RL	MDL
75-71-8	Dichlorodifluoromethane	0.055	U	0.055	0.016
74-87-3	Chloromethane	0.055	U	0.055	0.011
75-01-4	Vinyl chloride	0.055	U	0.055	0.010
74-83-9	Bromomethane	0.055	U	0.055	0.021
75-00-3	Chloroethane	0.055	U	0.055	0.015
75-69-4	Trichlorofluoromethane	0.055	U	0,055	0.011
75-35-4	1,1-Dichloroethene	0.055	U	0.055	0.012
75-15-0	Carbon disulfide	0.055	U	0,055	0.0094
67-64-1	Acetone	0.056		0.055	0.023
75-09-2	Methylene Chloride	0.055	υ	0.055	0.020
156-60-5	trans-1, 2-Dichloroethene	0.055	U	0.055	0.0095
1634-04-4	Methyl tert-butyl ether	0.055	U	0.055	0.0096
75-34-3	1,1-Dichloroethane	0.055	U	0.055	0.0067
594-20-7	2,2-Dichloropropane	0.055	U	0.055	0.011
156-59-2	cis-1,2-Dichloroethene	0.055	U	0.055	0.0083
78-93-3	2-Butanone (MEK)	0.055	U	0.055	0.025
74-97-5	Bromochloromethane	0.055	U	0.055	0.0093
67-66-3	Chloroform	0.055	υ	0.055	0.0079
71-55-6	1,1,1-Trichloroethane	0.055	U	0.055	0.0092
563-58-6	1,1-Dichloropropene	0.055	U	0.055	0.011
56-23-5	Carbon tetrachloride	0.055	U	0.055	0.013
71-43-2	Benzene	0.055	ti	0.055	0.0080
107-06-2	1,2-Dichloroethane	0.055	U	0.055	0.0089
79-01-6	Trichloroethene	0.055	U	0.055	0.0084
78-87-5	1,2-Dichloropropane	0.055	U	0.055	0.0082
74-95-3	Dibromomethane	0.055	U	0.055	0.0079
75-27-4	Bromodichloromethane	0.055	U	0.055	0.0085
10061-01-5	cis-1,3-Dichloropropene	0.055	U	0.055	0.0055
108-10-1	4-Methyl-2-pentanone (MIBK)	0.055	U	0.055	0.011
108-88-3	Toluene	0.055	U	0.055	0.0079
10061-02-6	trans-1,3-Dichloropropene	0.055	U	0.055	0.0081
79-00-5	1,1,2-Trichloroethane	0.055	U	0.055	0.011
127-18-4	Tetrachloroethene	0.055	U	0.055	0.010
142-28-9	1,3-Dichloropropane	0.055	U	0,055	0.0086
591-78-6	2-Hexanone	0.055	υ	0.055	0.027
124-48-1	Dibromochloromethane	0.055	U	0.055	0.0081

The 06/23/2011

Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG No.:

Client Sample ID: RP-SOLID-04 Lab Sample ID: 500-35461-12

Matrix: Solid Lab File ID: 5461-13B.D

Analysis Method: 8260B Date Collected: 06/13/2011 12:45

Sample wt/vol: 5(g) Date Analyzed: 06/22/2011 13:23

Soil Aliquot Vol: Dilution Factor: 10

Soil Extract Vol.: GC Column: DB624 ID: 0.2 (mm)

% Moisture: 9.6 Level: (low/med) Low

CAS NO.	COMPOUND NAME	RESULT	Q	RL	MDL
106-93-4	1,2-Dibromoethane	0.055	U I	0.055	0.0090
108-90-7	Chlorobenzene	0.055	U	0.055	0.0092
630-20-6	1,1,1,2-Tetrachloroethane	0.055	U	0.055	0.010
100-41-4	Ethylbenzene	0.055	U	0.055	0.0089
179601-23-1	m&p-Xylene	0.11	U	0.11	0.017
95-47-6	o-Xylene	0.055	U	0.055	0.0096
100-42-5	Styrene	0.055	U	0.055	0.0091
75-25-2	Bromoform	0.055	Ü	0.055	0.0090
98-82-8	Isopropylbenzene	0.055	U	0.055	0.011
108-86-1	Bromobenzene	0.055	U	0.055	0.0098
79-34-5	1,1,2,2-Tetrachloroethane	0.055	ti	0.055	0.0081
96-18-4	1,2,3-Trichloropropane	0.055	U	0.055	0.0086
103-65-1	N-Propylbenzene	0,055	U	0.055	0.0094
95-49-8	2-Chlorotoluene	0.055	U	0.055	0.010
108-67-8	1,3,5-Trimethylbenzene	0.055	U	0.055	0.010
106-43-4	4-Chlorotoluene	0.055	U	0.055	0.010
98-06-6	tert-Butylbenzene	0.055	U	0.055	0.010
95-63-6	1,2,4-Trimethylbenzene	0.055	U	0.055	0.011
135-98-8	sec-Butylbenzene	0.055	U	0.055	0.011
99-87-6	p-Isopropyltoluene	0.055	U	0.055	0.010
104-51-8	n-Butylbenzene	0.055	U.	0.055	0.011
96-12-8	1,2-Dibromo-3-Chloropropane	0.055	U	0.055	0.0093
87-61-6	1,2,3-Trichlorobenzene	0.055	U	0.055	0.017

CAS NO.	SURROGATE	%REC	Q	LIMITS
17060-07-0	1,2-Dichloroethane-d4 (Surr)	104		69-120
2037-26-5	Toluene-d8 (Surr)	97		69-122
460-00-4	4-Bromofluorobenzene (Surr)	101		67-120
1868-53-7	Dibromofluoromethane	111		69-120



Lab Name: TestAmerica Chicago	Job No.: 500-35461-1
SDG No.:	
Client Sample ID: RP-SOLID-04	Lab Sample ID: 500-35461-12
Matrix: Solid (TCLP)	Lab File ID: 35461-12.D
Analysis Method: 8260B	Date Collected: 06/13/2011 12:45
Sample wt/vol: 5(mL)	Date Analyzed: 06/21/2011 22:27
Soil Aliquot Vol:	Dilution Factor: 20
Soil Extract Vol.:	GC Column: DB624 ID: 0.2(mm)
% Moisture:	Level: (low/med) Low
Analysis Batch No.: 117161	Units: mg/L

CAS NO.	COMPOUND NAME	RESULT	Q	RL	MDL
71-43-2	Benzene	0.020	U	0.020	0.010
56-23-5	Carbon tetrachloride	0.020	U.	0.020	0,010
108-90-7	Chlorobenzene	0.020	U	0.020	0.010
67-66-3	Chloroform	0.020	U	0.020	0.010
107-06-2	1,2-Dichloroethane	0.020	U	0.020	0.010
75-35-4	1,1-Dichloroethene	0.020	U	0.020	0.010
78-93-3	2-Butanone (MEK)	0.10	U	0.10	0.050
127-18-4	Tetrachloroethene	0.020	U	0.020	0.010
79-01-6	Trichloroethene	0.020	U	0.020	0.010
75-01-4	Vinyl chloride	0.020	U	0.020	0.010

CAS NO.	SURROGATE	*REC	Q	LIMITS
17060-07-0	1,2-Dichloroethane-d4 (Surr)	95		77-124
2037-26-5	Toluene-d8 (Surr)	106		80-121
460-00-4	4-Bromofluorobenzene (Surr)	92		77-112
1868-53-7	Dibromofluoromethane	102		78-119



# Method 8270C

Semivolatile Organic Compounds (GC/MS) by Method 8270C

Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG No.:

Client Sample ID: RP-SOLID-01 Lab Sample ID: 500-35461-2

Matrix: Solid Lab File ID: 35461-2.D

Analysis Method: 8270C Date Collected: 06/13/2011 12:10

Extract. Method: 3541 Date Extracted: 06/16/2011 17:34

Sample wt/vol: 15.2433(g) Date Analyzed: 06/17/2011 18:58

Con. Extract Vol.: 0.5(mL) Dilution Factor: 1

Injection Volume: 1(uL) Level: (low/med) Low

% Moisture: 7.5 GPC Cleanup: (Y/N) N

CAS NO.	COMPOUND NAME	RESULT	Q	RL	MDL
108-95-2	PhenoI	0.18	U	0.18	0.037
111-44-4	Bis(2-chloroethyl)ether	0.18	n	0.18	0.020
541-73-1	1,3-Dichlorobenzene	0.18	U	0.18	0.019
106-46-7	1,4-Dichlorobenzene	0.18	U	0.18	0.020
95-50-1	1,2-Dichlorobenzene	0.18	U	0.18	0.019
100-51-6	Benzyl alcohol	0.35	U	0.35	0.092
95-48-7	2-Methylphenol	0.18	U	0.18	0.026
15831-10-4	3 & 4 Methylphenol	0.18	U	0.18	0.035
108-60-1	bis (2-chloroisopropyl) ether	0.18	U	0.18	0.038
621-64-7	N-Nitrosodi-n-propylamine	0.18	U	0.18	0.024
67-72-1	Hexachloroethane	0.18	U	0.18	0.027
95-57-8	2-Chlorophenol	0.18	U	0.18	0.018
98-95-3	Nitrobenzene	0.035	U	0.035	0.0085
111-91-1	Bis(2-chloroethoxy)methans	0.18	U	0.18	0.014
120-82-1	1,2,4-Trichlorobenzene	0.18	n.	0.18	0.022
65-85-0	Benzoic acid	1.8	0 ^ @	1.8	0.34
78-59-1	Isophorone	0.18	U	0.18	0.079
105-67-9	2,4-Dimethylphenol	0.35	U	0.35	0.12
87-68-3	Hexachlorobutadiene	0.18	U	0.18	0.027
91-20-3	Naphthalene	0.57		0.035	0.0064
120-83-2	2,4-Dichlorophenol	0.35	U	0.35	0.045
106-47-8	4-Chloroaniline	0.71	U	0.71	0.11
88-06-2	2,4,6-Trichlorophenol	0.35	U	0.35	0.076
95-95-4	2,4,5-Trichlorophenol	0.35	U	0.35	0.079
77-47-4	Hexachlorocyclopentadiene	0.71	U	0.71	0.35
91-57-6	2-Methylnaphthalene	0.89		0.18	0.014
88-74-4	2-Nitroaniline	0.18	U	0.18	0.021
91-58-7	2-Chloronaphthalene	0.18	U	0.18	0.014
59-50-7	4-Chloro-3-methylphenol	0.35	U	0.35	0.086
606-20-2	2,6-Dinitrotoluene	0.18	U	0.18	0.024
88-75-5	2-Nitrophenol	0.35	U	0.35	0.10
99-09-2	3-Nitroaniline	0.35	υ	0.35	0.061
131-11-3	Dimethyl phthalate	0.18	U	0.18	0.016
51-28-5	2,4-Dinitrophenol	0.71	U	0.71	0.26



Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG No.:

Client Sample ID: RP-SOLID-01 Lab Sample ID: 500-35461-2

Matrix: Solid Lab File ID: 35461-2.D

Analysis Method: 8270C Date Collected: 06/13/2011 12:10

Extract. Method: 3541 Date Extracted: 06/16/2011 17:34

Sample wt/vol: 15.2433(g) Date Analyzed: 06/17/2011 18:58

Con. Extract Vol.: 0.5(mL) Dilution Factor: 1

Injection Volume: 1(uL) Level: (low/med) Low

Moisture: 7.5 GPC Cleanup: (Y/N) N

CAS NO.	COMPOUND NAME	RESULT	Q	RL	MDL
208-96-8	Acenaphthylene	0.044		0.035	0.0055
121-14-2	2,4-Dinitrotoluene	0.18	U	0.18	0.036
83-32-9	Acenaphthene	0.035	U	0.035	0.0074
132-64-9	Dibenzofuran	0.25		0.18	0.040
100-02-7	4-Nitrophenol	0.71	0	0.71	0.28
86-73-7	Fluorene	0.060		0.035	0.0067
100-01-6	4-Nitroaniline	0.35	U	0.35	0.061
101-55-3	4-Bromophenyl phenyl ether	0.18	U	0.18	0.022
118-74-1	Hexachlorobenzene	0.071	U	0.071	0.0068
84-66-2	Diethyl phthalate	0.18	U	0,18	0.038
7005-72-3	4-Chlorophenyl phenyl ether	0.18	U	0.18	0.039
87-86-5	Pentachlorophenol	0.71	U	0.71	0.12
86-30-6	N-Nitrosodiphenylamine	0.18	U	0.18	0.019
534-52-1	4,6-Dinitro-2-methylphenol	0.35	U	0.35	0.067
85-01-8	Phenanthrene	0.75		0.035	0.0069
120-12-7	Anthracene	0.12		0.035	0.0065
86-74-8	Carbazole	0.071	J	0.18	0.019
84-74-2	Di-n-butyl phthalate	0.18	ti .	0.18	0.020
206-44-0	Fluoranthene	0.75		0.035	0.0066
129-00-0	Pyrene	0.58		0.035	0.012
85-68-7	Butyl benzyl phthalate	0.18	U	0.18	0.030
56-55-3	Benzo[a]anthracene	0.36		0.035	0.0076
218-01-9	Chrysene	0.40		0.035	0.011
91-94-1	3,3'-Dichlorobenzidine	0.18	U	0,18	0.026
117-81-7	Bis(2-ethylhexyl) phthalate	0.089	J	0,18	0.019
117-84-0	Di-n-octyl phthalate	0.18	U	0.18	0.028
205-99-2	Benzo[b]fluoranthene	0.38		0.035	0.0073
207-08-9	Benzo[k]fluoranthene	0.16		0.035	0.0083
50-32-8	Benzo[a]pyrene	0.29		0.035	0.0068
193-39-5	Indeno[1,2,3-cd]pyrene	0.13		0.035	0.0090
53-70-3	Dibenz(a,h)anthracene	0,057		0.035	0.0089
191-24-2	Benzo[g,h,i]perylene	0.19		0.035	0.0086



Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG No.:

Client Sample ID: RP-SOLID-01 Lab Sample ID: 500-35461-2

Matrix: Solid Lab File ID: 35461-2.D

Analysis Method: 8270C Date Collected: 06/13/2011 12:10

Extract. Method: 3541 Date Extracted: 06/16/2011 17:34

Sample wt/vol: 15.2433(g) Date Analyzed: 06/17/2011 18:58

Con. Extract Vol.: 0.5(mL) Dilution Factor: 1

Injection Volume: 1(uL) Level: (low/med) Low

% Moisture: 7.5 GPC Cleanup: (Y/N) N

CAS NO.	SURROGATE	FREC	Q	LIMITS
367-12-4	2-Fluorophenol	67		30-110
4165-62-2	Phenol-d5	81		26-112
4165-60-0	Nitrobenzene-d5	80		22-110
321-60-8	2-Fluorobiphenyl	92		27-113
118-79-6	2,4,6-Tribromophenol	89		30-137
1718-51-0	Terphenyl-d14	90		33-129



Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG No.:

Client Sample ID: RP-SOLID-01 Lab Sample ID: 500-35461-2

Matrix: Solid (TCLP) Lab File ID: 35461-2.D

Analysis Method: 8270C Date Collected: 06/13/2011 12:10

Extract, Method: 3510C Date Extracted: 06/20/2011 10:45

Sample wt/vol: 100(mL) Date Analyzed: 06/21/2011 17:25

Con. Extract Vol.: 1.0(mL) Dilution Factor: 1

Injection Volume: 1(uL) Level: (low/med) Low

Moisture: GPC Cleanup: (Y/N) N

CAS NO.	COMPOUND NAME	RESULT	Q	RL	MDL
95-48-7	2-Methyl-phenol	0.10	U	0.10	0.050
15831-10-4	3 & 4 Methylphenol	0.10	U	0.10	0.050
106-46-7	1,4-Dichlorobenzene	0.10	U	0.10	0.050
121-14-2	2,4-Dinitrotoluene	0.10	-D	0.10	0.050
118-74-1	Hexachlorobenzene	0.10	ti	0.10	0.050
87-68-3	Hexachloro-1,3-butadiene	0.10	U	0.10	0.050
67-72-1	Hexachloroethane	0.10	Ü	0.10	0.050
98-95-3	Nitrobenzene	0.10	U	0,10	0.050
87-86-5	Pentachlorophenol	0.50	U	0.50	0.25
110-86-1	Pyridine	0.20	U ^ Q	0.20	0.10
95-95-4	2,4,5-Trichlorophenol	0.50	U ,	0.50	0.25
88-06-2	2,4,6-Trichlorophenol	0.10	U	0.10	0.050

CAS NO.	SURROGATE	*REC	Q	LIMITS
367-12-4	2-Fluorophenol	39		20-100
4165-62-2	Phenol-d5	27		20-100
4165-60-0	Nitrobenzene-d5	74		39-110
321-60-8	2-Fluorobiphenyl	84		44-110
118-79-6	2,4,6-Tribromophenol	88		46-126
1718-51-0	Terphenyl-d14	92		52-131

Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG No.:

Client Sample ID: RP-SOLID-02 Lab Sample ID: 500-35461-3

Matrix: Solid Lab File ID: 35461-3.D

Analysis Method: 8270C Date Collected: 06/13/2011 12:20

Extract. Method: 3541 Date Extracted: 06/16/2011 17:34

Sample wt/vol: 15.1466(g) Date Analyzed: 06/17/2011 19:20

Con. Extract Vol.: 25.0 (mL) Dilution Factor: 5

Injection Volume: 1(uL) Level: (low/med) Low

% Moisture: 34.4 GPC Cleanup: (Y/N) N

CAS NO.	COMPOUND NAME	RESULT	Q	RL	MDL
108-95-2	Phenol	63	U	63	13
111-44-4	Bis(2-chloroethyl)ether	63	U	63	7.2
541-73-1	1,3-Dichlorobenzene	63	U.	63	6.9
106-46-7	1,4-Dichlorobenzene	63	U	63	7.1
95-50-1	1,2-Dichlorobenzene	63	U	63	6.8
100-51-6	Benzyl alcohol	120	t	120	33
95-48-7	2-Methylphenol	63	U	63	9.3
15831-10-4	3 & 4 Methylphenol	63	U	63	13
108-60-1	bis (2-chloroisopropyl) ether	63	U	63	14
621-64-7	N-Nitrosodi-n-propylamine	63	U	63	8.7
67-72-1	Hexachloroethane	63	U	63	9.5
95-57-8	2-Chlorophenol	63	U	63	6.5
98-95-3	Nitrobenzene	12	U	12	3.0
111-91-1	Bis(2-chloroethoxy)methane	63	U	63	5.1
120-82-1	1,2,4-Trichlorobenzene	63	U	63	7.7
65-85-0	Benzoic acid	630	TION (Q)	630	120
78-59-1	Isophorone	63	U	63	28
105-67-9	2,4-Dimethylphenol	120	U	120	41
87-68-3	Hexachlorobutadiene	63	U	63	9.7
91-20-3	Naphthalene	12	Ü	12	2.3
120-83-2	2,4-Dichlorophenol	120	U	120	16
106-47-8	4-Chloroaniline	250	U	250	40
88-06-2	2,4,6-Trichlorophenol	120	U	120	27
95-95-4	2,4,5-Trichlorophenol	120	U	120	28
77-47-4	Hexachlorocyclopentadiene	250	U	250	120
91-57-6	2-Methylnaphthalene	63	U	63	4.9
88-74-4	2-Nitroaniline	63	U	63	73
91-58-7	2-Chloronaphthalene	63	U	63	5.0
59-50-7	4-Chloro-3-methylphenol	120	U	120	31
606-20-2	2,6-Dinitrotoluene	63	U	63	8.4
88-75-5	2-Nitrophenol	120	U	120	37
99-09-2	3-Nitroaniline	120	Ü	120	22
131-11-3	Dimethyl phthalate	63	U	63	5.5
51-28-5	2,4-Dinitrophenol	250	D .	250	92



Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG No.:

Client Sample ID: RP-SOLID-02 Lab Sample ID: 500-35461-3

Matrix: Solid Lab File ID: 35461-3.D

Analysis Method: 8270C Date Collected: 06/13/2011 12:20

Extract. Method: 3541 Date Extracted: 06/16/2011 17:34

Sample wt/vol: 15.1466(g) Date Analyzed: 06/17/2011 19:20

Con. Extract Vol.: 25.0 (mL) Dilution Factor: 5

Injection Volume: 1(uL) Level: (low/med) Low

# Moisture: 34.4 GPC Cleanup: (Y/N) N

CAS NO.	COMPOUND NAME	RESULT	Q	RL	MDL
208-96-8	Acenaphthylene	12	U	12	1.9
121-14-2	2,4-Dinitrotoluene	63	U	63	13
83-32-9	Acenaphthene	12	U	12	2.6
132-64-9	Dibenzofuran	63	Ü	63	14
100-02-7	4-Nitrophenol	250	U	250	100
86-73-7	Fluorene	12	U	12	2.4
100-01-6	4-Nitroaniline	120	IJ	120	21
101-55-3	4-Bromophenyl phenyl ether	63	Ð	63	7.7
118-74-1	Hexachlorobenzene	25	U	25	2.4
84-66-2	Diethyl phthalate	63	U	63	14
7005-72-3	4-Chlorophenyl phenyl ether	63	U	63	14
87-86-5	Pentachlorophenol	250	U U	250	41
86-30-6	N-Nitrosodiphenylamine	63	U	63	6.8
534-52-1	4,6-Dinitro-2-methylphenol	120	tt	120	24
85-01-8	Phenanthrene	12	IJ	12	2.5
120-12-7	Anthracene	12	U	12	2.3
86-74-8	Carbazole	63	D.	63	6.9
84-74-2	Di-n-butyl phthalate	63	U	63	6.9
206-44-0	Fluoranthene	12	Ü	12	2.3
129-00-0	Pyrene	6.1	J	12	4.3
85-68-7	Butyl benzyl phthalate	63	U	63	10
56-55-3	Benzo[a]anthracene	12	Ü	12	2.7
218-01-9	Chrysene	12	D	12	4.0
91-94-1	3,3'-Dichlorobenzidine	63	U	63	9.2
117-81-7	Bis(2-ethylhexyl) phthalate	24	J	63	6.8
117-84-0	Di-n-octyl phthalate	63	U .	63	10
205-99-2	Benzo[b]fluoranthene	12	U	12	2.6
207-08-9	Benzo[k]fluoranthene	12	0	12	2.9
50-32-8	Benzo[a]pyrene	-12	-U	12	2.4
193-39-5	Indeno[1,2,3-cd]pyrene	12	U	12	3.2
53-70-3	Dibenz(a,h)anthracene	12	U	12	3.2
191-24-2	Benzo[g,h,i]perylene	12	B B	12	3.1



Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG No.:

Client Sample ID: RP-SOLID-02 Lab Sample ID: 500-35461-3

Matrix: Solid Lab File ID: 35461-3.D

Analysis Method: 8270C Date Collected: 06/13/2011 12:20

Extract, Method: 3541 Date Extracted: 06/16/2011 17:34

Sample wt/vol: 15.1466(g) Date Analyzed: 06/17/2011 19:20

Con. Extract Vol.: 25.0 (mL) Dilution Factor: 5

Injection Volume: 1(uL) Level: (low/med) Low

% Moisture: 34.4 GPC Cleanup: (Y/N) N

CAS NO.	SURROGATE	% REC	Q	LIMITS
367-12-4	2-Fluorophenol	0	D	30-110
4165-62-2	PhenoI-d5	0	D	26-112
4165-60-0	Nitrobenzene-d5	0.	D	22-110
321-60-8	2-Fluorobiphenyl	G	D.	27-113
118-79-6	2,4,6-Tribromophenol	0	D	30+137
1718-51-0	Terphenyl-d14	0	D	33-129

Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG No.:

Client Sample ID: RP-SOLID-02 Lab Sample ID: 500-35461-3

Matrix: Solid (TCLP) Lab File ID: 35461-3.D

Analysis Method: 8270C Date Collected: 06/13/2011 12:20

Extract. Method: 3510C Date Extracted: 06/20/2011 10:45

Sample wt/vol: 100(mL) Date Analyzed: 06/21/2011 17:48

Con. Extract Vol.: 1.0(mL) Dilution Factor: 1

Injection Volume: 1(uL) Level: (low/med) Low

# Moisture: GPC Cleanup: (Y/N) N

CAS NO.	COMPOUND NAME	RESULT	Q	RL	MDL
95-48-7	2-Methyl-phenol	0.10	U	0.10	0.050
15831-10-4	3 & 4 Methylphenol	0.10	U	0.10	0.050
106-46-7	1,4-Dichlorobenzene	0.10	U	0.10	0.050
121-14-2	2,4-Dinitrotoluene	0.10	D	0.10	0.050
118-74-1	Hexachlorobenzene	0.10	U	0.10	0.050
87-68-3	Hexachloro-1,3-butadiene	0.10	U	0.10	0.050
67-72-1	Hexachloroethane	0,10	U	0,10	0.050
98-95-3	Nitrobenzene	0.10	υ	0.10	0.050
87-86-5	Pentachlorophenol	0.50	U	0.50	0.25
110-86-1	Pyridine	0.20	U ^ Q	0.20	0.10
95-95-4	2,4,5-Trichlorophenol	0.50	U	0.50	0.25
88-06-2	2,4,6-Trichlorophenol	0.10	U	0.10	0.050

CAS NO.	SURROGATE	WREC	Q	LIMITS
367-12-4	2-Fluorophenol	34		20-100
4165-62-2	Phenol-d5	2.6		20-100
4165-60-0	Nitrobenzene-d5	68		39-110
321-60-8	2-Fluorobiphenyl	71:		44-110
118-79-6	2,4,6-Tribromophenol	91		46-126
1718-51-0	Terphenyl-d14	87		52-131



Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG No.:

Client Sample ID: RP-SOLID-03 Lab Sample ID: 500-35461-4

Matrix: Solid Lab File ID: 35461-4.D

Analysis Method: 8270C Date Collected: 06/13/2011 12:30

Extract. Method: 3541 Date Extracted: 06/16/2011 17:34

Sample wt/vol: 15.2747(g) Date Analyzed: 06/17/2011 19:41

Con. Extract Vol.: 25.0 (mL) Dilution Factor: 5

Injection Volume: 1(uL) Level: (low/med) Low

% Moisture: 6.2 GPC Cleanup: (Y/N) N

CAS NO.	COMPOUND NAME	RESULT	Q	RL	MDL
108-95-2	Phenol	44	U	44	9.1
111-44-4	Bis(2-chloroethyl)ether	44	U	44	5.0
541-73-1	1,3-Dichlorobenzene	44	υ	44:	4.8
106-46-7	1,4-Dichlorobenzene	4.4	U	44	4.9
95-50-1	1,2-Dichlorobenzene	44	υ	44	4.7
100-51-6	Benzyl alcohol	86	U	86	23
95-48-7	2-Methylphenol	44	υ	4.4	6.5
15831-10-4	3 & 4 Methylphenol	44	U	44	8.7
108-60-1	bis (2-chloroisopropyl) ether	44	U	44	9.4
621-64-7	N-Nitrosodi-n-propylamine	4.4	Ü	44	6.0
67-72-1	Hexachloroethane	44	U	44	6.6
95-57-8	2-Chlorophenol	44	υ	44	4.5
98-95-3	Nitrobenzene	6.6	U	8.6	2.1
111-91-1	Bis(2-chloroethoxy)methane	4.4	Ü	4.4	3.5
120-82-1	1,2,4-Trichlorobenzene	44	υ	44	5.3
65-85-0	Benzoic acid	440	Unio	440	83
78-59-1	Isophorone	44	U )	44	19
105-67-9	2,4-Dimethylphenol	86	U	86	29
87-68-3	Hexachlorobutadiene	4.4	U	44	6.7
91-20-3	Naphthalene	8.6	U	8.6	1.6
120-83-2	2,4-Dichlorophenol	.86	U	86	11
106-47-8	4-Chloroaniline	180	υ	180	27
88-06-2	2,4,6-Trichlorophenol	86	U	86	19
95-95-4	2,4,5-Trichlorophenol	86	U	86	19
77-47-4	Hexachlorocyclopentadiene	180	U	180	8.6
91-57-6	2-Methylnaphthalene	- 44	0	44	3.4
88-74-4	2-Nitroaniline	44	U:	44	5.1
91-58-7	2-Chloronaphthalene	44	D.	:44:	3.5
59-50-7	4-Chloro-3-methylphenol	86	-D	86	21
606-20-2	2,6-Dinitrotoluene	44	U	44	5.8
88-75-5	2-Nitrophenol	B6	U	86	26
99-09-2	3-Nitroaniline	86	0	86	15
131-11-3	Dimethyl phthalate	44	U	44	3.8
51-28-5	2,4-Dinitrophenol	180	U	180	64



Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG No.:

Client Sample ID: RP-SOLID-03 Lab Sample ID: 500-35461-4

Matrix: Solid Lab File ID: 35461-4.D

Analysis Method: 8270C Date Collected: 06/13/2011 12:30

Extract. Method: 3541 Date Extracted: 06/16/2011 17:34

Sample wt/vol: 15.2747(g) Date Analyzed: 06/17/2011 19:41

Con. Extract Vol.: 25.0 (mL) Dilution Factor: 5

Injection Volume: 1(uL) Level: (low/med) Low

% Moisture: 6.2 GPC Cleanup: (Y/N) N

CAS NO.	COMPOUND NAME	RESULT	0	RL	MDL
208-96-8	Acenaphthylene	8.6	U	8.6	1.3
121-14-2	2,4-Dinitrotoluene	44	U	44	8.9
83-32-9	Acenaphthene	8.6	a a	8.6	1.8
132-64-9	Dibenzofuran	44	0	44	9.9
100-02-7	4-Nitrophenol	180	U	180	70
86-73-7	Fluorene	8.6	U	8.6	1.7
100-01-6	4-Nitroaniline	86	U	86	15
101-55-3	4-Bromophenyl phenyl ether	44	U	44	5.3
118-74-1	Hexachlorobenzene	18	U	18	1.7
84-66-2	Diethyl phthalate	44	U	44	9.5
7005-72-3	4-Chlorophenyl phenyl ether	44	U	44	9.6
87-86-5	Pentachlorophenol	180	U	180	29
86-30-6	N-Nitrosodiphenylamine	44.	U	4.4	4.7
534-52-1	4,6-Dinitro-2-methylphenol	86	t)	86	16
85-01-8	Phenanthrene	9.4		8.6	1.7
120-12-7	Anthracene	3.0	J	8.6	1.6
86-74-8	Carbazole	44	U	44	4.8
84-74-2	Di-n-butyl phthalate	44	U	44	4.8
206-44-0	Fluoranthene	4.3	J	8.6	1.6
129-00-0	Pyrene	10		8.6	3.0
85-68-7	Butyl benzyl phthalate	44	U	44	7.3
56-55-3	Benzo[a]anthracene	3.1	J	8.6	1.9
218-01-9	Chrysene	8.6	U	8.6	2.8
91-94-1	3,3'-Dichlorobenzidine	4.4	O.	44	6.4
117-81-7	Bis(2-ethylhexyl) phthalate	44	0	44	4.7
117-84-0	Di-n-octyl phthalate	44	U.	44	7.0
205-99-2	Benzo[b]fluoranthene	8.6	Ü	8.6	1.8
207-08-9	Benzo[k]fluoranthene	8.6	Ü	8.6	2.0
50-32-8	Benzo[a]pyrene	8.6	U	8.6	1.7
193-39-5	Indeno[1,2,3-cd]pyrene	8.6	U	8.6	2.2
53-70-3	Dibenz(a,h)anthracene	8.6	U	8.6	2.2
191-24-2	Benzo(g,h,i)perylene	8.6	U	8.6	2.1



Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG No.:

Client Sample ID: RP-SOLID-03 Lab Sample ID: 500-35461-4

Matrix: Solid Lab File ID: 35461-4.D

Analysis Method: 8270C Date Collected: 06/13/2011 12:30

Extract. Method: 3541 Date Extracted: 06/16/2011 17:34

Sample wt/vol: 15.2747(g) Date Analyzed: 06/17/2011 19:41

Con. Extract Vol.: 25.0(mL) Dilution Factor: 5

Injection Volume: 1(uL) Level: (low/med) Low

% Moisture: 6.2 GPC Cleanup: (Y/N) N

CAS NO.	SURROGATE	*REC	Q	LIMITS
367-12-4	2-Fluorophenol	0	D	30-110
4165-62-2	Phenol-d5	0	D	26-112
4165-60-0	Nitrobenzene-d5	0	D	22-110
321-60-8	2-Fluorobiphenyl	0	D:	27-113
118-79-6	2,4,6-Tribromophenol	0	D'	30-137
1718-51-0	Terphenyl-d14	0	D	33-129

Lab Name: TestAmerica Chicago Job No.: 500-35461-1 SDG No.: Client Sample ID: RP-SOLID-03 Lab Sample ID: 500-35461-4 Matrix: Solid (TCLP) Lab File ID: 35461-4.D Analysis Method: 8270C Date Collected: 06/13/2011 12:30 Extract. Method: 3510C Date Extracted: 06/20/2011 10:45 Sample wt/vol: 100(mL) Date Analyzed: 06/21/2011 18:11 Con. Extract Vol.: 1.0(mL) Dilution Factor: 1 Injection Volume: 1(uL) Level: (low/med) Low % Moisture: GPC Cleanup: (Y/N) N Analysis Batch No.: 117119 Units: mg/L

CAS NO.	COMPOUND NAME	RESULT	Q	RL	MDL
95-48-7	2-Methyl-phenol	0.10	Ü	0.10	0.050
15831-10-4	3 & 4 Methylphenol	0.10	U	0.10	0.050
106-46-7	1,4-Dichlorobenzene	0.10	U	0.10	0.050
121-14-2	2,4-Dinitrotoluene	0.10	Ü	0.10	0.050
118-74-1	Hexachlorobenzene	0.10	U	0.10	0.050
87-68-3	Hexachloro-1, 3-butadiene	0.10	U	0.10	0.050
67-72-1	Hexachloroethane	0.10	U	0.10	0.050
98-95-3	Nitrobenzene	0.10	U	0.10	0.050
87-86-5	Pentachlorophenol	0.50	U	0.50	0.25
110-86-1	Pyridine	0.20	U 1 0	0.20	0.10
95-95-4	2,4,5-Trichlorophenol	0.50	U	0.50	0.25
88-06-2	2,4,6-Trichlorophenol	0.10	D:	0.10	0.050

CAS NO.	SURROGATE	#REC	Q	LIMITS
367-12-4	2-Fluorophenol	39		20-100
4165-62-2	Pheno1-d5	32		20+100
4165-60-0	Nitrobenzene-d5	63		39-110
321-60-8	2-Fluorobiphenyl	77		44-110
118-79-6	2,4,6-Tribromophenol	92		46-126
1718-51-0	Terphenyl-d14	88		52-131

Lab Name: TestAmerica Chicago Job No.: 500-35461-1 SDG No.: Client Sample ID: RP-DRUM-07 Lab Sample ID: 500-35461-11 Matrix: Water Lab File ID: 35461-11.D Analysis Method: 8270C Date Collected: 06/13/2011 14:30 Extract. Method: 3510C Date Extracted: 06/20/2011 08:15 Sample wt/vol: 100(mL) Date Analyzed: 06/22/2011 01:02 Con. Extract Vol.: 15.0(mL) Dilution Factor: 10 Injection Volume: 1(uL) Level: (low/med) Low % Moisture: GPC Cleanup: (Y/N) N Analysis Batch No.: 117118 Units: mg/L

CAS NO. COMPOUND NAME RESULT 0 RL MDL 108-95-2 Phenol 7.5 0 7.5 111-44-4 Bis(2-chloroethyl)ether 3.0 U 3.0

541-73-1	1,3-Dichlorobenzene	3.0	ti	3.0	0.32
106-46-7	1,4-Dichlorobenzene	3.0	U	3.0	0.36
95-50-1	1,2-Dichlorobenzene	3.0	U	3.0	0.38
100-51-6	Benzyl alcohol	30	U	30	7.4
95-48-7	2-Methylphenol	3.0	U .	3.0	0.38
15831-10-4	3 & 4 Methylphenol	3.0	U	3.0	0.38
108-60-1	bis (2-chloroisopropyl) ether	3.0	U	3.0	0.39
621-64-7	N-Nitrosodi-n-propylamine	0.75	U	0.75	0.23
67-72-1	Hexachloroethane	7.5	ū	7.5	1.8
95-57-8	2-Chlorophenol	7.5	U	7.5	1.7
98-95-3	Nitrobenzene	1.5	U	1.5	0.56
111-91-1	Bis(2-chloroethoxy)methane	3.0	U	3.0	0.39
120-82-1	1,2,4-Trichlorobenzene	3.0	U	3.0	0.39
65-85-0	Benzoic acid	30	U * * O	30	7.1
78-59-1	Isophorone	3.0	U	3.0	0.39
105-67-9	2,4-Dimethylphenol	15	U	15	2.4
87-68-3	Hexachlorobutadiene	7.5	U	7.5	2.3
91-20-3	Naphthalene	1.5	U	1.5	0.21
120-83-2	2,4-Dichlorophenol	15	U	15	1.5
106-47-8	4-Chloroaniline	15	U	15	2.0
88-06-2	2,4,6-Trichlorophenol	7.5	U	7.5	1.7
95-95-4	2,4,5-Trichlorophenol	15	U	15	2.7
77-47-4	Hexachlorocyclopentadiene	30	n	30	8.3
91-57-6	2-Methylnaphthalene	0.75	υ	0.75	0.23
88-74-4	2-Nitroaniline	7.5	U	7.5	2.1
91-58-7	2-Chloronaphthalene	3.0	U	3.0	0.33
59-50-7	4-Chloro-3-methylphenol	15	U	15	2.1
606-20-2	2,6-Dinitrotoluene	0.75	U	0.75	0.20
88-75-5	2-Nitrophenol	15	U	15	2.1
99-09-2	3-Nitroaniline	15	U	15	2.9
131-11-3	Dimethyl phthalate	3.0	U	3.0	1.1
51-28-5	2,4-Dinitrophenol	30	U	30	12

1.2

0.68

Lab Name: TestAmerica Chicago	Job No.: 500-35461-1
SDG No.:	
Client Sample ID: RP-DRUM-07	Lab Sample ID: 500-35461-11
Matrix: Water	Lab File ID: 35461-11.D
Analysis Method: 8270C	Date Collected: 06/13/2011 14:30
Extract. Method: 3510C	Date Extracted: 06/20/2011 08:15
Sample wt/vol: 100(mL)	Date Analyzed: 06/22/2011 01:02
Con. Extract Vol.: 15.0 (mL)	Dilution Factor: 10
Injection Volume: 1(uL)	Level: (low/med) Low
% Moisture:	GPC Cleanup: (Y/N) N
Analysis Batch No.: 117118	Units: mg/L

CAS NO.	COMPOUND NAME	RESULT	Q	RL	MDL
208-96-8	Acenaphthylene	1.5	U	1.5	0.15
121-14-2	2,4-Dinitrotoluene	1.5	ti	1.5	0.42
83-32-9	Acenaphthene	1.5	U	1.5	0.14
132-64-9	Dibenzofuran	3.0	U	3.0	0.42
100-02-7	4-Nitrophenol	30	U	30	5.6
86-73-7	Fluorene	1.5	U	1,5	0.18
100-01-6	4-Nitroaniline	1.5	U	15	3.0
101-55-3	4-Bromophenyl phenyl ether	7.5	U	7.5	2.1
118-74-1	Hexachlorobenzene	0.75	U	0.75	0.14
84-66-2	Diethyl phthalate	3.0	ū	3.0	0.47
7005-72-3	4-Chlorophenyl phenyl ether	7.5	U	7.5	2.0
87-86-5	Pentachlorophenol	30	0 * /	30	4.8
86-30-6	N-Nitrosodiphenylamine	1.5	U	1.5	0.38
534-52-1	4,6-Dinitro-2-methylphenol	30	U	30	7,5
85-01-8	Phenanthrene	1.5	U	1.5	0.12
120-12-7	Anthracene	1.5	U	1.5	0.18
86-74-8	Carbazole	7.5	U	7.5	2.0
84-74-2	Di-n-butyl phthalate	7.5	U	7.5	1.8
206-44-0	Fluoranthene	1.5	0	1.5	0.15
129-00-0	Pyrene	1.5	U	1.5	0.14
85-68-7	Butyl benzyl phthalate	3.0	U	3.0	0.45
56-55-3	Benzo[a]anthracene	0.30	U	0.30	0.081
218-01-9	Chrysene	0.75	U	0.75	0.17
91-94-1	3,3'-Dichlorobenzidine	7.5	U	7.5	2.0
117-81-7	Bis(2-ethylhexyl) phthalate	15	U	15	1.8
117-84-0	Di-n-octyl phthalate	15	U	15	2.4
205-99-2	Benzo[b]fluoranthene	0.30	U	0.30	0.10
207-08-9	Benzo[k]fluoranthene	0.30	0 * (3)	0.30	0.14
50-32-8	Benzo[a]pyrene	0.30	U	0.30	0.068
193-39-5	Indeno[1,2,3-cd]pyrene	0.30	U	0.30	0.099
53-70-3	Dibenz(a,h)anthracene	0.45	U	0.45	0.18
191-24-2	Benzo(g,h,i)perylene	1.5	U	1.5	0.17

3 Pg 11 06/23/2011

Lab Name: TestAmerica Chicago Job No.: 500-35461-1 SDG No.: Client Sample ID: RP-DRUM-07 Lab Sample ID: 500-35461-11 Matrix: Water Lab File ID: 35461-11.D Analysis Method: 8270C Date Collected: 06/13/2011 14:30 Extract, Method: 3510C Date Extracted: 06/20/2011 08:15 Sample wt/vol: 100(mL) Date Analyzed: 06/22/2011 01:02 Con. Extract Vol.: 15.0(mL) Dilution Factor: 10 Injection Volume: 1(uL) Level: (low/med) Low % Moisture: GPC Cleanup: (Y/N) N Analysis Batch No.: 117118 Units: mg/L

CAS NO.	SURROGATE	*REC	Q	LIMITS
367~12~4	2-Fluorophenol	0	D:	20-100
4165-62-2	Phenol-d5	0	D:	20-100
4165-60-0	Nitrobenzene-d5	0	D	39-110
321-60-8	2-Fluorobiphenyl	0	D.	44-110
118-79-6	2,4,6-Tribromophenol	0	Đ	46-126
1718-51-0	Terphenyl-d14	0	D	52-131

Lab Name: TestAmerica Chicago Job No.: 500-35461-1 SDG No.: Client Sample ID: RP-DRUM-07 Lab Sample ID: 500-35461-11 Matrix: Water (TCLP) Lab File ID: 35461-11.D Analysis Method: 8270C Date Collected: 06/13/2011 14:30 Extract. Method: 3510C Date Extracted: 06/20/2011 10:45 Sample wt/vol: 100(mL) Date Analyzed: 06/21/2011 18:34 Con. Extract Vol.: 15.0 (mL) Dilution Factor: 10 Injection Volume: 1(uL) Level: (low/med) Low # Moisture: GPC Cleanup: (Y/N) N Analysis Batch No.: 117119 Units: mg/L

CAS NO.	COMPOUND NAME	RESULT	Q	RL	MDL
95-48-7	2-Methyl-phenol	15	U	15	7.5
15831-10-4	3 & 4 Methylphenol	15	U	15	7.5
106-46-7	1,4-Dichlorobenzene	15	.0	15	7.5
121-14-2	2,4-Dinitrotoluene	15	U	15	7.5
118-74-1	Hexachlorobenzene	15	t	15	7.5
87-68-3	Hexachloro-1,3-butadiene	15	U	15	7.5
67-72-1	Hexachloroethane	15	U	15	7.5
98-95-3	Nitrobenzene	15	U	15	7.5
87-86-5	Pentachlorophenol	75	U	75	38
110-86-1	Pyridine	30	U ^ (2)	30	15
95-95-4	2,4,5-Trichlorophenol	75	n	75	38
88-06-2	2,4,6-Trichlorophenol	15	Ü	15	7.5

CAS NO.	SURROGATE	*REC	Q	LIMITS	
367-12-4	2-Fluorophenol	0	D	20-100	
4165-62-2	Phenol-d5	0	D-	20-100	
4165-60-0	Nitrobenzene-d5	0	D:	39-110	
321-60-8	2-Fluorobiphenyl	0	D	44-110	
118-79-6	2,4,6-Tribromophenol	0	D	46-126	
1718-51-0	Terphenyl-dl4	0	D:	52-131	

Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG No.:

Client Sample ID: RP-SOLID-04 Lab Sample ID: 500-35461-12

Matrix: Solid Lab File ID: 35461-12.D

Analysis Method: 8270C Date Collected: 06/13/2011 12:45

Extract. Method: 3541 Date Extracted: 06/16/2011 17:34

Sample wt/vol: 5.8078(g) Date Analyzed: 06/17/2011 20:03

Con. Extract Vol.: 0.5(mL) Dilution Factor: 1

Injection Volume: 1(uL) Level: (low/med) Low

% Moisture: 9.6 GPC Cleanup: (Y/N) N

CAS NO.	COMPOUND NAME	RESULT	Q	RL	MDL
108-95-2	Phenol	0.48	U	0.48	0.099
111-44-4	Bis(2-chloroethyl)ether	0.48	U	0.48	0.055
541-73-1	1,3-Dichlorobenzene	0.48	U	0.48	0.052
106-46-7	1,4-Dichlorobenzene	0.48	U	0.48	0.053
95-50-1	1,2-Dichlorobenzene	0.48	U	0.48	0.051
100-51-6	Benzyl alcohol	0.94	U	0.94	0.25
95-48-7	2-Methylphenol	0.48	υ	0.48	0.071
15831-10-4	3 & 4 Methylphenol	0.48	U	0.48	0.095
108-60-1	bis (2-chloroisopropyl) ether	0.48	U	0.48	0.10
621-64-7	N-Nitrosodi-n-propylamine	0.48	U	0.48	0.066
67-72-1	Hexachloroethane	0.48	U	0.48	0.072
95-57-8	2-Chlorophenol	0.48	U	0.48	0.049
98-95-3	Nitrobenzene	0.094	U	0.094	0.023
111-91-1	Bis(2-chloroethoxy)methane	0.48	U	0.48	0.039
120-82-1	1,2,4-Trichlorobenzene	0.48	U	0.48	0.058
65-85-0	Benzoic acid	4.8	0.00	4.8	0.91
78-59-1	Isophorone	0.48	U	0.48	0.21
105-67-9	2,4-Dimethylphenol	0.94	U	0.94	0.31
87-68-3	Hexachlorobutadiene	0.48	U	0.48	0.073
91-20-3	Naphthalene	0.094	U	0.094	0.017
120-83-2	2,4-Dichlorophenol	0.94	D.	0.94	0.12
106-47-8	4-Chloroaniline	1.9	U	1.9	0.30
88-06-2	2,4,6-Trichlorophenol	0.94	U	0.94	0.20
95-95-4	2,4,5-Trichlorophenol	0.94	U	0.94	0.21
77-47-4	Hexachlorocyclopentadiene	1.9	U	1.9	0.94
91-57-6	2-Methylnaphthalene	0.48	U	0.48	0.037
88-74-4	2-Nitroaniline	0.48	υ	0.48	0.055
91-58-7	2-Chloronaphthalene	0.48	U	0.48	0.038
59-50-7	4-Chloro-3-methylphenol	0.94	U	0.94	0.23
606-20-2	2,6-Dinitrotoluene	0.48	U	0.48	0.063
88-75-5	2-Nitrophenol	0.94	U	0.94	0.28
99-09-2	3-Nitroaniline	0.94	U	0.94	0.17
131-11-3	Dimethyl phthalate	0,48	υ	0.48	0.042
51-28-5	2,4-Dinitrophenol	1.9	ti	1.9	0.70



Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG No.:

Client Sample ID: RP-SOLID-04 Lab Sample ID: 500-35461-12

Matrix: Solid Lab File ID: 35461-12.D

Analysis Method: 8270C Date Collected: 06/13/2011 12:45

Extract. Method: 3541 Date Extracted: 06/16/2011 17:34

Sample wt/vol: 5.8078(g) Date Analyzed: 06/17/2011 20:03

Con. Extract Vol.: 0.5(mL) Dilution Factor: 1

Injection Volume: 1(uL) Level: (low/med) Low

% Moisture: 9.6 GPC Cleanup: (Y/N) N

CAS NO.	COMPOUND NAME	RESULT	Q	RL	MDL
208-96-8	Acenaphthylene	0.094	U	0.094	0.015
121-14-2	2,4-Dinitrotoluene	0.48	U	0.48	0.098
83-32-9	Acenaphthene	0.094	·U	0.094	0.020
132-64-9	Dibenzofuran	0.48	U	0.48	0.11
100-02-7	4-Nitrophenol	1.9	U	1.9	0.77
86-73-7	Fluorene	0.094	U	0.094	0.018
100-01-6	4-Nitroaniline	0.94	U	0.94	0.16
101-55-3	4-Bromophenyl phenyl ether	0.48	U	0.48	0.058
118-74-1	Hexachlorobenzene	0.19	U	0.19	0.018
84-66-2	Diethyl phthalate	0.48	U	0.48	0.10
7005-72-3	4-Chlorophenyl phenyl ether	0.48	U	0.48	0.10
87-86-5	Pentachlorophenol	1.9	U	1.9	0.31
86-30-6	N-Nitrosodiphenylamine	0.19	3	0.48	0.052
534-52-1	4,6-Dinitro-2-methylphenol	0.94	U	0.94	0.18
85-01-8	Phenanthrene	0,27		0.094	0.019
120-12-7	Anthracene	0.094	U	0.094	0.017
86-74-8	Carbazole	0.48	U	0.48	0.052
84-74-2	Di-n-butyl phthalate	0.48	U	0.48	0.053
206-44-0	Fluoranthene	0.15		0.094	0.018
129-00-0	Pyrene	0.31		0.094	0.033
85-68-7	Butyl benzyl phthalate	0.94		0.48	0.079
56-55-3	Benzo[a]anthracene	0.094	U	0.094	0.020
218-01-9	Chrysene	0.094	U	0.094	0.030
91-94-1	3,3'-Dichlorobenzidine	0.48	U	0.49	0.070
117-81-7	Bis(2-ethylhexyl) phthalate	2.0		0.48	0.052
117-84-0	Di-n-octyl phthalate	0.48	U	0.48	0.076
205-99-2	Benzo[b]fluoranthene	0.094	U	0.094	0.020
207-08-9	Benzo[k]fluoranthene	0.094	U	0.094	0.022
50-32-8	Benzo[a]pyrene	0.094	U	0.094	0.018
193-39-5	Indeno[1,2,3-od]pyrene	0.094	Ü	0.094	0.024
53-70-3	Dibenz(a,h)anthracene	0.094	U	0.094	0.024
191-24-2	Benzo[g,h,i]perylene	0.094	U	0.094	0.023



Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG No.:

Client Sample ID: RF-SOLID-04 Lab Sample ID: 500-35461-12

Matrix: Solid Lab File ID: 35461-12.D

Analysis Method: 8270C Date Collected: 06/13/2011 12:45

Extract. Method: 3541 Date Extracted: 06/16/2011 17:34

Sample wt/vol: 5.8078(g) Date Analyzed: 06/17/2011 20:03

Con. Extract Vol.: 0.5(mL) Dilution Factor: 1

Injection Volume: 1(uL) Level: (low/med) Low

% Moisture: 9.6 GPC Cleanup: (Y/N) N

CAS NO.	SURROGATE	%REC	Q	LIMITS
367-12-4	2-Fluorophenol	63		30-110
4165-62-2	Phenol-d5	78		26-112
4165-60-0	Nitrobenzene-d5	66		22-110
321-60-8	2-Fluorobiphenyl	76		27-113
118-79-6	2,4,6-Tribromophenol	91.		30-137
1718-51-0	Terphenyl-dl4	103		33-129



Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG No.:

Client Sample ID: RP-SOLID-04 Lab Sample ID: 500-35461-12

Matrix: Solid (TCLP) Lab File ID: 35461-12.D

Analysis Method: 8270C Date Collected: 06/13/2011 12:45

Extract. Method: 3510C Date Extracted: 06/20/2011 10:45

Sample wt/vol: 100(mL) Date Analyzed: 06/21/2011 18:58

Con. Extract Vol.: 1.0(mL) Bilution Factor: 1

Injection Volume: 1(uL) Level: (low/med) Low

% Moisture: GPC Cleanup: (Y/N) N

CAS NO.	COMPOUND NAME	RESULT	Q	RL	MDL
95-48-7	2-Methyl-phenol	0.10	U	0.10	0.050
15831-10-4	3 & 4 Methylphenol	0.10	U	0.10	0.050
106-46-7	1,4-Dichlorobenzene	0.10	U	0.10	0.050
121-14-2	2,4-Dinitrotoluene	0.10	U	0.10	0.050
118-74-1	Hexachlorobenzene	0.10	U	0.10	0.050
87-68-3	Hexachloro-1,3-butadiene	0.10	U	0.10	0.050
67-72-1	Hexachloroethane	0.10	U	0.10	0.050
98-95-3	Nitrobenzene	0.10	U	0.10	0.050
87-86-5	Pentachlorophenol	0.50	U	0.50	0.25
110-86-1	Pyridine	0.20	U ^ ()	0.20	0.10
95-95-4	2,4,5-Trichlorophenol	0.50	U	0.50	0.25
88-06-2	2,4,6-Trichlorophenol	0.10	U	0.10	0.050

CAS NO.	SURROGATE	%REC	Q	LIMITS	
367-12-4	2-Fluorophenol	17	x Q	20-100	
4165-62-2	Pheno1-d5	26	- 1	20-100	
4165-60-0	Nitrobenzene-d5	68		39-110	
321-60-8	2-Fluorobiphenyl	76		44-110	
118-79-6	2,4,6-Tribromophenol	100		46-126	
1718-51-0	Terphenyl-d14	59		52-131	



### Method 8082

Polychlorinated Biphenyls (PCBs) by Gas Chromatography by Method 8082

#### FORM I PCBS ORGANICS ANALYSIS DATA SHEET

Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG No.:

Client Sample ID: RP-SOLID-02 Lab Sample ID: 500-35461-3

Matrix: Solid Lab File ID: 061311\_094.D

Analysis Method: 8082 Date Collected: 06/13/2011 12:20

Extraction Method: 3541 Date Extracted: 06/16/2011 19:05

Sample wt/vol: 15.8526(g) Date Analyzed: 06/17/2011 13:10


Con. Extract Vol.: 25.0 (mL) Dilution Factor: 1

Injection Volume: 1(uL) GC Column: RTX-5 ID: 0.53(mm)

Moisture: 34.4 GPC Cleanup: (Y/N) N

CAS NO.	COMPOUND NAME	RESULT	Q	RL	MDL
12674-11-2	PCB-1016	0.12	U	0.12	0.029
11104-28-2	PCB-1221	0.12	U	0.12	0.045
11141-16-5	PCB-1232	0.12	ū	0.12	0.042
53469-21-9	PCB-1242	0.12	U	0.12	0.037
12672-29-6	PCB-1248	0.12	Ü	0.12	0.041
11097-69-1	PCB-1254	0.12	U	0.12	0.037
11096-82-5	PCB-1260	0.12	U	0.12	0.039

CAS NO. SURROGATE		*REC	Q	LIMITS
877-09-8	Tetrachloro-m-xylene	175	p X /	28-124
2051-24-3	DCB Decachlorobiphenyl	172	pX	38-130



#### FORM I PCBS ORGANICS ANALYSIS DATA SHEET

Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG No.:

Client Sample ID: RP-SOLID-03 Lab Sample ID: 500-35461-4

Matrix: Solid Lab File ID: 061311\_095.D

Analysis Method: 8082 Date Collected: 06/13/2011 12:30

Extraction Method: 3541 Date Extracted: 06/16/2011 19:05

Sample wt/vol: 15.6477(g) Date Analyzed: 06/17/2011 13:24

Con. Extract Vol.: 25.0 (mL) Dilution Factor: 1

Injection Volume: 1(uL) GC Column: RTX-5 ID: 0.53(mm)

% Moisture: 6.2 GPC Cleanup: (Y/N) N

CAS NO.	COMPOUND NAME	RESULT	Q	RL	MDL
12674-11-2	PCB-1016	0.085	U	0.085	0.020
11104-28-2	PCB-1221	0.085	U	0.085	0.032
11141-16-5	PCB-1232	0.085	Ü	0.085	0.030
53469-21-9	PCB-1242	0.085	U	0.085	0.026
12672-29-6	PCB-1248	0.085	U	0.085	0.029
11097-69-1	PCB-1254	0.085	U	0.085	0.027
11096-82-5	PCB-1260	0.085	U	0.085	0.028

CAS NO.	SURROGATE	%REC	Q	LIMITS	
877-09-8	Tetrachloro-m-xylene	81	p Q	28-124	
2051-24-3	DCB Decachlorobiphenyl	101	p ()	38-130	



# **METALS**

#### 1A-IN INORGANIC ANALYSIS DATA SHEET METALS

Client Sample ID: RF-SOLID-01 Lab Sample ID: 500-35461-2

Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG ID.:

Matrix: Solid Date Sampled: 06/13/2011 12:10

Reporting Basis: DRY Date Received: 06/15/2011 17:15

% Solids: 92.5

CAS No.	Analyte	Result	RL	MDL	Units	C	0	DIL	Method
7440-38-2	Arsenic	12	0,93	0.13	mg/Kg	1		1	6010B
7440-39-3	Barium	48	0.93	0.052	mg/Kg			1	6010B
7440-43-9	Cadmium	0.25	0.19	0.025	mg/Kg			1:	6010B
7440-47-3	Chromium	11	0.93	0.079	mg/Kg		В	1	6010B
7440-50-8	Copper	29	0.93	0.13	mg/Kg			1	6010B
7439-92-1	Lead	43	0.46	0,22	mg/Kg			1	6010B
7782-49-2	Selenium	0.49	0.93	0.26	mg/Kg	J		1	6010B
7440-22-4	Silver	0.46	0.46	0.058	mg/Kg	U		1	6010B
7440-66-6	Zinc	50	1.9	0.15	mg/Kg			1	6010B
7439-97-6	Mercury	0.078	0.017	0.0017	mg/Kg	_	_	1	74718



#### IA-IN INORGANIC ANALYSIS DATA SHEET METALS - TCLP

Client Sample ID: RP-SOLID-01 Lab Sample ID: 500-35461-2

Lab Name: TestAmerica Chicago Job No.: 500-35461+1

SDG ID.:

Matrix: Solid Date Sampled: 06/13/2011 12:10

CAS No.	Analyte	Result	RL	MDL	Units	C	0	DIL	Method
7440-38-2	Arsenic	0.050	0.050	0.010	mg/L	U		- 1	6010B
7440-39-3	Barium	0.25	0.50	0.010	mg/L	J		1	6010B
7440-43-9	Cadmium	0.0050	0.0050	0.0020	mg/L	0		1	6010B
7440-47-3	Chromium	0.025	0.025	0.010	mg/L	U		1	6010B
7440-50-8	Copper	0.011	0.025	0.010	mg/L	3	В	1	60108
7439-92-1	Lead	0.0081	0.050	0.0050	mg/L	3		1	6010B
7782-49-2	Selenium	0.050	0.050	0.010	mg/L	Ü		- 1	6010B
7440-22-4	Silver	0.025	0.025	0.0050	mg/L	U		- 1	6010B
7440-66-6	Zinc	0.17	0.10	0.020	mg/L			1	6010B
7439-97-6	Mercury	0.0020	0.0020	0.00020	mg/L	U		1	7470A

#### 1A-IN INORGANIC ANALYSIS DATA SHEET METALS

Client Sample ID: RP-SOLID-02 Lab Sample ID: 500-35461-3

Lab Name: TestAmerica Chicago Job No.: 500-35461-1


SDG ID.:

Matrix: Solid Date Sampled: 06/13/2011 12:20

Reporting Basis: DRY Date Received: 06/15/2011 17:15

% Solids: 65.6

CAS No.	Analyte	Result	RL	MDI,	Units	C	Q	DIL	Method
7440-38-2	Arsenic	9.9	1.4	0.19	mg/Kg			1	6010B
7440-39-3	Barium	360	1,4	0.076	mg/Kg			1	6010B
7440-43-9	Cadmium	1.4	0.27	0.037	mg/Kg			1	6010B
7440-47-3	Chromium	27	1.4	0.12	mg/Kg		8	1	6010B
7440-50-8	Copper	250	1.4	0.19	mg/Kg			1	6010B
7439-92-1	Lead	390	0.68	0.33	mg/Kg			1	6010B
7782-49-2	Selenium	1.4	1.4	0.38	mg/Kg	U		1	6010B
7440-22-4	Silver	0.33	0.68	0.086	mg/Kg	3		1	6010B
7440-66-6	Zinc	460	2.7	0.22	mg/Kg			1	6010B
7439-97-6	Mercury	0.036	0.024	0.0024	mq/Kq			1	7471A



#### IA-IN INORGANIC ANALYSIS DATA SHEET METALS - TCLP

Client Sample ID: RP-SOLID-02 Lab Sample ID: 500-35461-3

Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG ID.:

Matrix: Solid Date Sampled: 06/13/2011 12:20

CAS No.	Analyte	Result	RL	MDL	Units	, C	.0	DIL	Method
7440-38-2	Arsenic	0.018	0.050	0.010	mg/L	J	1	1	60109
7440-39-3	Barium	0.12	0.50	0.010	mg/L	J		1	6010B
7440-43-9	Cadmium	0.0050	0.0050	0.0020	mg/L	U		1	6010B
7440-47-3	Chromium	0.025	0.025	0.010	mg/L	U		1	6010B
7440-50-8	Copper	0.070	0.025	0.010	mg/L		В	1	6010B
7439-92-1	Lead	0.11	0.050	0.0050	mg/L			1	6010B
7782-49-2	Selenium	0.050	0.050	0.010	mg/L	U		- 1	6010B
7440-22-4	Silver	0.025	0.025	0.0050	mg/L	ū		1	6010B
7440-66-6	Zinc	0.60	0.10	0.020	mg/L		_	1	6010B
7439-97-6	Mercury	0.0020	0.0020	0.00020	mg/L	U		1	7470A

## IA-IN INORGANIC ANALYSIS DATA SHEET METALS

Client Sample ID: RP-SOLID-03 Lab Sample ID: 500-35461-4

Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG ID.:

Matrix: Solid Date Sampled: 06/13/2011 12:30

Reporting Basis: DRY Date Received: 06/15/2011 17:15

% Solids: 93.8

CAS No.	Analyte	Result	RL	MDL	Units	C	0	DIL	Method
7440-38-2	Arsenic	9,6	0.98	0.14	mg/Kg	1		1.	6010B
7440-39-3	Barium	200	0.98	0.055	mg/Kg			1	6010B
7440-43-9	Cadmium	2.2	0.20	0.026	mg/Kg			1	6010B
7440-47-3	Chromium	32	0.98	0.083	mg/Kg		Б	1.	6010B
7440-50-8	Copper	280	0.98	0.14	mg/Kg			1	6010B
7439-92-1	Lead	1600	0.49	0.23	mg/Kg			1.	6010B
7782-49-2	Selenium	0.52	0.98	0.27	mg/Kg	J		1.	6010B
7440-22-4	Silver	0.43	0.49	0.062	mg/Kg	J		1	6010B
7440-66-6	Zinc	260	2.0	0.16	mg/Kg			1.	6010B
7439-97-6	Mercury	0.053	0.016	0.0017	mg/Kg			1.	7471A

#### 1A-IN INORGANIC ANALYSIS DATA SHEET METALS - TCLP

Client Sample ID: RP-SOLID-03 Lab Sample ID: 500-35461-4

Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG ID.:

Matrix: Solid Date Sampled: 06/13/2011 12:30

CAS No.	Analyte	Result	RL	MDL	Units	0	0	DIL	Method
7440-38-2	Arsenic	0.050	0.050	0.010	mg/L	D.		1	6010B
7440-39-3	Barium	0.075	0.50	0.010	mg/L	J		1	6010B
7440-43-9	Cadmium	0.0028	0.0050	0.0020	mg/L	3		- 1	60108
7440-47-3	Chromium	0.025	0.025	0.010	mg/L	U		1	6010B
7440-50-8	Copper	0.14	0.025	0.010	mg/L		В	1	6010B
7439-92-1	Lead	0.32	0.050	0.0050	mg/L		1177	- 1	6010B
7782-49-2	Selenium	0.050	0.050	0,010	mg/L	U		- 1	6010B
7440-22-4	Silver	0.025	0.025	0.0050	mg/L	U		- 1	6010B
7440-66-6	Zinc	0.77	0.10	0.020	mg/L			1	6010B
7439-97-6	Mercury	0.0020	0.0020	0.00020	mg/L	U		1	7470A

#### IA-IN INORGANIC ANALYSIS DATA SHEET METALS

Client Sample ID: RP-SOLID-04 Lab Sample ID: 500-35461-12

Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG ID.:

Matrix: Solid Date Sampled: 06/13/2011 12:45

Reporting Basis: DRY Date Received: 06/15/2011 17:15

E Solids: 90.4

CAS No.	Analyte	Result	RL	MDL	Units	C	0	DIL	Method
7440-38-2	Arsenic	0.48	1.1	0.15	mg/Kg	J		1	6010B
7440-39-3	Barium	36	1.1	0.061	mg/Kg			- 1	6010B
7440-43-9	Cadmium	0.21	0.22	0.029	mg/Kg	3:		1	6010B
7440-47-3	Chromium	15	1,1	0.092	mg/Kg		В	1	6010B
7440-50-8	Copper	82	1.1	0.15	mg/Kg			1	6010B
7439-92-1	Lead	15	0.54	0.26	mg/Kg			- 1	6010B
7782-49-2	Selenium	0.39	1.1	0.30	mg/Kg	3		- 1	6010B
7440-22-4	Silver	0.13	0.54	0.068	mg/Kg	J		- 1	6010B
7440-66-6	Zinc	65	2.2	0.17	mg/Kg	-		1	6010B
7439-97-6	Mercury	0.11	0.018	0.0018	mg/Kg	_	_	1	7471A

#### 1A-IN INORGANIC ANALYSIS DATA SHEET METALS - TCLP

Client Sample ID: RP-SOLID-04 Lab Sample ID: 500-35461-12

Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG ID.:

Matrix: Solid Date Sampled: 06/13/2011 12:45

CAS No.	Analyte	Result	RL	MDL	Units	С	0	DIL	Method
7440-38-2	Arsenic	0.050	0.050	0.010	mg/L	U		1	6010B
7440-39-3	Barium	0.50	0.50	0.010	mg/L			1	6010B
7440-43-9	Cadmium	0.0055	0.0050	0.0020	mg/L			1	6010B
7440-47-3	Chromium	0.052	0.025	0.010	mg/L			1	6010B
7440-50-8	Copper	0.71	0.025	0.010	mg/L			1	6010B
7439-92-1	Lead	0.040	0,050	0.0050	mg/L	J		1	6010B
7782-49-2	Selenium	0.050	0.050	0.010	mg/L	U		1	6010B
7440-22-4	Silver	0.025	0.025	0.0050	mg/L	U		1	6010B
7440-66-6	Zinc	1.0	0.10	0.020	mg/L			- 1	6010B
7439-97-6	Mercury	0.0020	0.0020	0.00020	mg/L	U		1	7470A



Client Sample ID: RP-DRUM-01 Lab Sample ID: 500-35461-5

Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG ID.:

Matrix: Water Date Sampled: 06/13/2011 13:30

CAS No.	Analyte	Result	RL	MDL	Units	С	0	DIL	Method
10	pH.	13.7	0.200	0.200	SU		HF	1	90408



Client Sample ID: RP-DRUM-02 Lab Sample ID: 500-35461-6


Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG ID.:

Matrix: Water Date Sampled: 06/13/2011 13:45

CAS No.	Analyte	Result	RL	MDL	Units	C	0	DIL	Method
	Flashpoint	>176	40	40	Degrees			1/	1010
	pH	11.0	0,200	0.200	SU		HF	1	9040B

Client Sample 1	ID: RP-DRUM-03			Lab Sample	ID: 500-	35461-	7		
Lab Name: Tes	tAmerica Chicago			Job No.:	500-35461-	1			
SDG ID.:									
Matrix: Water				Date Sampl	ed: 06/13	/2011	13:50		
Reporting Basis	s: WET		Date Recei	ved: 06/1	5/2011	17:15			
CAS No.	CAS No. Analyte Result RL				Units	С	0	DIL	Method
	pH 12.3 0.2				SU		HF	1	9040B



Client Sample ID: RP-DRUM-04 Lab Sample ID: 500-35461-8

Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG ID.:

Matrix: Water Date Sampled: 06/13/2011 13:55

CAS No.	Analyte	Result	RL	MDL	Units	C	0	DIL	Method
	Flashpoint	>176	40	40	Degrees F			1	1010
	pH	8.46	0.200	0.200	sti		HF	1	9040B



Client Sample ID: RP-DRUM-05 Lab Sample ID: 500-35461-9
Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG ID.:

Matrix: Water Date Sampled: 06/13/2011 14:00

CAS No.	Analyte	Result	RL	MDL	Units	C	0	DIL	Method
	Flashpoint	140	40	40	Degrees			1	1010
	pH	11.8	0.200	0.200	SU		HF	1	9040B

Client Sample	ID: RP-DRUM-06			Lab Sample	ID: 500	-35461-	10		
Lab Name: Te	stAmerica Chicago			Job No.:	500-35461	-1			
SDG ID.:									
Matrix: Wate	rix: Water				ed: 06/1	3/2011	15:00		
Reporting Bas	porting Basis: WET					15/2011	17:15		
CAS No.	Analyte	Result	RL	MDL	Units	C	Q	DIL	Method
	pH 0.200 0.20				su	U	HF	1	9040B



Client Sample ID: RP-DRUM-07 Lab Sample ID: 500-35461-11

Lab Name: TestAmerica Chicago Job No.: 500-35461-1

SDG ID.:

Matrix: Water Date Sampled: 06/13/2011 14:30

CAS No.	Analyte	Result	RL	MDL	Units	C	Q	DIL	Method
	pH	12.6	0.200	0.200	SU		HF	1	9040B



	Flashpoint	140	40	40	Degrees			1	1010
CAS No.	Analyte	Result	RL	MDL	Units	C	0	DIL	Method

1936 Olney Avenue, Cherry Hill, NJ 08003

(866) 871-1984 Fax (856) 489-4085 www.emlab.com

Client: TestAmerica-University Park, IL

C/O: Marilyn Krueding

Re: 50005626; Rockford Paperboard

Date of Sampling: 06-13-2011 Date of Receipt: 06-17-2011 Date of Report: 06-21-2011

#### ASBESTOS PLM REPORT: EPA-600/M4-82-020 & EPA METHOD 600/R-93-116

Total Samples Submitted:

Total Samples Analysed: 1

Total Samples with Layer Asbestos Content > 1%: 0

Location: RP-AS-01, (500-35461-1) Lab ID-Version: 3524674-1

6	The transfer of the second
Sample Layers	Asbestos Content
Multicolored Semi-Fibrous Material	ND
Composite Non-Asbestos Fibrous Content:	10% Cellulose
Sample Composite Homogeneity:	Moderate

The results relate only to the items tested. Interpretation is left to the company and/or persons who conducted the field work. The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government.

All samples were received in acceptable condition unless otherwise noted. EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed.

‡ A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

EMLab P&K, LLC

EMLab ID: 795827, Page 2 of 2

Page 1315 of 1322

06/23/2011

# ATTACHMENT CHAIN-OF-CUSTODY

THE LEADER IN ENVIRONMENTAL TESTING 2417 Bond Street, University Park, IL 60484 Phone: 708.534,5200 Fax: 708.534,5211	Report To Contact: Company: Address: Phone:	(орвоп	nal)		Bill To Contact Company: Address:_ Address:_ Phone:		(optional)			. Lab Jo	of Custody Record  to 1500 - 3546    of Custody Number:
	Fax:			-	Facc					Temp	erature *C of Cooler:
Client Compets	E-Mail:	Preservative			PO#/Refere	nose				1	Preservative Key  1. HCL Cool to 4*
Project Name ROUKFORD PARERBOR Project Location/State ROCKFORD, M. I.  Samedor	reD.	Parameter	ă	di	3	ship to			Xr		2. H2SO4, Cool to 4* 3. HNO3, Cool to 4* 4. NaCH, Cool to 4* 5. NaCHZn, Cool to 4* 6. NaHSO4
Sampler Waren Balm/EW Lat PM Mar	lyn Knedin	7	Seghos	202	220	etar o met	PLB.	4	12		7. Cool to 4º 8. Nome 9. Other
O GS NUSSAN Sample ID	Sampling Date Time	# of Containers Matrix	184	137	Sofor	Potal MIE		PH	Flackforing		Convents
1 RP-45-01	6/13/11 120	01 1	X	)6	Bec.	100	SOR SOR				4
2 RP- SOUP-01	1 1210	2-9	,	×	×	X		40-10-000			Soil
3 RP- SOL10- 62.	122	023		×	×	×	×				
4 RP- 5040-63	123	23		×	×	×	X				
5 RP- PRUM-0)	133	0 1 MS	5					X			@Product/waste
6 RP- DRUM-02	134	511						X	×		1
7 RP- DRUM-03	1350	1						X			
8 R9- DROM-04	1355	1						×	×		
9 RP-DRUM-05	140	03		X				×	×		1
10 RP-DRUM-06	150							×			possible Hydrochionic
Turnaround Time Required (Business Days)1 Day2 Days7 Days10 Days	15 Days Other	Sample Dispo	osali n to Client	Disp	posal by Lab	Archi	ve for	_ Months	(A fee may t	be assessed if sample	is are istained longer than 1 month)
Refinite(shed By  Company  Refinite(shed By  Company	Date   5 11	Time	Received By	die.P	ncker	company company		Date Date	/31	1715 Time	Lab Courier Shipped
Refinquished By Company	Date	Time	Received By		c	Company		Date		Time	Hand Delivered
Matrix Key	Handle w heada	ith co	are. D	ilm h's	nd ma sample	y be	ab Comments:	midel Stemaker Steries N			

Page 20 of 23

A – Air

06/28/2011

TestAmerica THE LEADER IN ENVIRONMENTAL TESTIN 2417 Bond Street, University Park, IL 60484 Phone: 708.534.5200 Fax: 708.534.5211	Company:	(optional)	(optional)  Bill To  Contact:  Company:  Address:  Address:  Phone:  Fux:  PO#/Ruference#	Chain of Custody Record  Lab Job #: 500 - 35 46 1  Chain of Custody Number:  Page
Client Projec	d i	Preservative		Preservative Key 1. HCL, Cool to 4*
Project Name ROYLFORD PAPER	BOARD	Parameter		2. H2SO4, Cool to 4* 3. HNO3, Cool to 4*
Project Location/State ROCKFORD, MI Lab Project		इत्तर		4. NeOH, Cool to 4" 5. NeOHZA, Cool to 4" 6. NeHSO4 7. Cool to 4" 8. None
O O O O O O O O O O O O O O O O O O O	Sampling Date Time	Containen Rear Rear Rear Rear Rear Rear Rear Rear	# =	9. Other
2 ≥ Sample ID	6/13/11 1430	1 1/2 X X	$\times$	Product Sample
12 RP- SOLIO-04	6 13 11 1245	11/2 / (		* added in login from
				Soc accord at the chieses.
Turneround Time Required (Business Days)		Sample Disposal		
Requested Due Date 2 Days 7 Days 10 Da	ys 15 Days Other	Return to Client Disp	osal by Lab Archive for Months	(A fee may be assessed if samples are retained longer than 1 month)
Refinquished By  Refinquished By  Company  Company  Company	06-15-11	Received By Received By	em TA OUISII	Time Lab Courier Shipped
Relinquished By Company	Dale T	Terms Received By	Company . Date	Time Hand Delivered
Matrix Key  WW - Wastewater  W - Water  S - Soil  L - Leschate  SL - Studge  WI - Wipe  MS Miscrettaneous  OL - Oil  A - Air	nt Comments	Page 21	Lab Convinents:	06/28/2011

	estAmerica	Con	ort i'e lact	Man	(optional)	B-02	~	Bill To Contact:		(optional)				N. 3 14 3	Gustody Re
THE	LEADER IN ENVIRONMENTAL TESTING 2417 Bond Shoot University Park, IL 80484. Prene: 708.634.6200 Fac: 708.634.6211	Add Add	rbss.					Address:	7 37 3 7 2 3 7 3 7 4 3 4 3			1		Chain of Gud	MERCHANIST NO
Client		Fax. E-M	* 1,21°	6), 14, 131	7)			PORFuture	mgall				20.00	Temperature	24 3134
	0 17 G		1.00	Presen	Yan Yo	36.47				30		1000			1, HCL, God 2, H2SO4, 0
Project No	ROLKFORD YAPERBOARD			Param	neter.	4	4	3 -							3. HNO3, Co 4. NaOH, Co 5. NaOH/Zn:
Bernpter	CID CLESORD, M.C. Lab Project 8	-				18 TZ	200	E TO					\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		8. NaHSO4 7. Cool to 4= 8. Hone 9. Other
9	Seruto KD	San Dels	griing	Containers	Mark	Popul	Potent.	Total				/.,			Comments
12	PP-SOLIP-04	6/13/11	1245	2		X	×	×	1 43	100			100		
4		min.	1		27	7 1	100	375	1 /2	1	. 74			S 1.3	4
	Herman Harris of the	11.11		. '	11,							,		* 5 . 4.	
74							1.7	11 4	1 1		·				
Ę.	And the desired a selection		120 1.			·	11 131	my in	14 40	10 11 1			2 . 10		
35.5		· ·	11.51		-		B					:1. ÷			
3				1.5		7.3		4	1			4			
4	1 18 5 2 8 5 5 7 1 1 1 1 1 1 1	11		2 1	7 . 4	4 . (	j		-	-			-	49.3	
-		-		y 5.	400		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1000	15	2.1				A	111
Ž.L	74 (7) 1) STAR FOR THE TARRETT		17.14	7.					N			38	ورسندا		<u></u>
- 1 Da	d Timo Required (Burindou Doys)  y 2 Days 7 Days 10 Days 1  Doe Date	5 Days	Other	4 .	Disposal Peturn to C	Olient	Disp	count by Lub	Archi	ve for	Months	(A fee may	be assessed it a	emplee are re	teined longer than 1 month)
Rainquiste	DO Carpeny	715/4	T	brok .	74 1	celveli tily			ampliny		Duts		Three		Leb Courier
elthipelishe	lBy Coppany 0	in the second	1	alle.	Ren	celved By		Q	Completely .	1	Dete		Diss	-	Shapped
Palingulaho	Dy Corregany D	lede	10	ene	Ra	Control By		C	belong		Date		Direi		and Delivered
WW - Wa	Mark Key Client Committee BE - Badiment	order .				11	3	7. 5		ab Commonts:	. ; ;	7.	) }		
W - Water 8 - Soll St Stude MS - Misc OL - Oll	L - Leschate . Wh - Wipe . Williamedte . DYV - Drinking Water .									Ena	led 4	no lus		enl .	06/ab(14
A-Air				P	age	22 01	E 23			_	_				06/28/2011

0 0 0